

EDUCATIONAL PLANT FIVE YEAR SURVEY REPORT

College: COLLEGE OF CENTRAL FLORIDA
Survey: Number 3 - Version 2
Survey Status: Active Pending

EDUCATIONAL PLANT FIVE YEAR SURVEY REPORT

College:

3-COLLEGE OF CENTRAL FLORIDA

Survey:

Survey : 3 Version : 2

Status:

Active Pending

EDUCATIONAL PLANT FIVE YEAR SURVEY REPORT

College:

3-COLLEGE OF CENTRAL FLORIDA

Survey:

Survey : 3 Version : 2

Status:

Active Pending

Section 1: Survey Details

EDUCATIONAL PLANT FIVE YEAR SURVEY REPORT

College:

3-COLLEGE OF CENTRAL FLORIDA

Survey:

Survey : 3 Version : 2

Status:

Active Pending

College: COLLEGE OF CENTRAL FLORIDA
Survey: Number 3 - Version 2
Description: Ocala Campus Building Remodels: #42 HS Expansion and #20 ATC
Survey Open Date: 7/11/2023 11:29:50 AM
Board Approval Date:
Survey Expiration Date: 6/30/2028
DVE768 Approval Date: 6/23/2022
Contact Name: Katherine Hunt
Contact Phone Number: 3528542322
Contact Email: huntk@cf.edu

Survey Status	Status Time	User
Active Pending	7/11/2023 11:29:50 AM	Anne Nyman1

Master Plan update on file: No

The following local governments have received a copy of the college's educational plant survey pursuant to Chapter 1013 Florida Statutes:

EDUCATIONAL PLANT FIVE YEAR SURVEY REPORT

College:

3-COLLEGE OF CENTRAL FLORIDA

Survey:

Survey : 3 Version : 2

Status:

Active Pending

Survey Notes : None Entered

Site Notes for: OCALA CAMPUS

EDUCATIONAL PLANT FIVE YEAR SURVEY REPORT

College:

3-COLLEGE OF CENTRAL FLORIDA

Survey:

Survey : 3 Version : 2

Status:

Active Pending

Section 2: Survey Cost Summary

EDUCATIONAL PLANT FIVE YEAR SURVEY REPORT

College:

3-COLLEGE OF CENTRAL FLORIDA

Survey:

Survey : 3 Version : 2

Status:

Active Pending

RECOMMENDATIONS FOR EDUCATIONAL PLANTS

COLLEGE OF CENTRAL FLORIDA

Survey : 3 Version : 2

Date : 10/10/2023 8:04:42 AM

The educational plant survey is a systematic study of present educational and ancillary plants and the determination of future needs. The survey is not directly concerned with the instructional program but the relationship of educational plants to the instructional program is such that judgments regarding the instructional program are necessarily a part of an educational plant survey.

The construction, remodeling, and renovation of educational facilities is a major undertaking. The educational plant survey aids in formulating plans for housing the educational activities of students and staff of the community college for the next several years and the survey considers the local comprehensive plan in its forecast strategies. This plan represents a careful study of all available data regarding the status of educational and ancillary facilities in relation to capital outlay full-time equivalency (COFTE) student membership and the projected changes in COFTE student membership. The intent of this educational plant survey is to ensure the thoughtful, orderly development of a program for providing educational and ancillary plants to house the educational and academic support activities of the college.

The recommendations in this educational plant survey furnish the foundation for a five-year plan for educational plants adopted by the Board of Trustees in accordance with §1013.31, Florida Statutes. Similarly, the recommendations serve as the basis for the proposed building program with projects listed in the order of priority submitted pursuant to State Requirements for Educational Facilities §2.1(5).

Educational plant survey cost estimates are determined based on cost factors that are 31 months (January, the midway point of the five-year survey period) from the official beginning of the survey period, which is July 1 of the first full year of the survey. The cost per square foot for new construction, remodeling, and renovation is based on actual statewide average construction cost data with a cost index increase applied to use the mid-point of the survey costs for planning purposes. The cost estimate process applies uniformly to all surveys in all colleges so that consistent planning can be made on a statewide basis.

Cost estimates for educational plant survey recommendations provide a general idea of anticipated costs and should not be interpreted as accurate estimates for particular projects. When educational plant survey recommendations become specific projects, professionals who can estimate the actual project costs based on current construction information must prepare the estimates.

The following table is a summary of square foot rates and cost estimates for the community college educational plant survey recommendations:

Recommendation Category	Cost per Square Foot	Estimated Cost
New Construction	445.00	52,805,035.00
Remodeling	490.76	6,146,784.00
Renovation	∞	41,650,949.00
Site Recommendations		22,838,169.00
Estimated Total Survey Recommendation Cost		123,440,937.00

In addition, the educational plant survey provides six standard recommendations for college-wide application, as needed. The standard survey recommendations address general categories of physical plant needs that are likely to occur over time. No cost estimates are included for the standard survey recommendations.

EDUCATIONAL PLANT FIVE YEAR SURVEY REPORT

College:

3-COLLEGE OF CENTRAL FLORIDA

Survey:

Survey : 3 Version : 2

Status:

Active Pending

Section 3: Expenditures By Project Type

EDUCATIONAL PLANT FIVE YEAR SURVEY REPORT

College:

3-COLLEGE OF CENTRAL FLORIDA

Survey:

Survey : 3 Version : 2

Status:

Active Pending

FUND EXPENDITURES BY PROJECT TYPE

Site : OCALA CAMPUS

Site Number : 1

Fund Name	2022 - 2023	2023 - 2024	2024 - 2025	2025 - 2026	2026 - 2027	5 Year Total
Planning	0	1,835,919	795,626	0	0	2,631,545
Land Acquisition	0	0	0	0	0	0
Building Construction	16,667,996	14,319,745	0	0	0	30,987,741
Furniture And Equipment	0	2,128,967	1,309,536	824,262	0	4,262,765
Remodeling, Renovation, Maintenance And Repair	28,579,573	0	5,563,766	0	0	34,143,339
Other Structures & Improvements	0	0	0	0	0	0
Library Books And Films	0	0	0	0	0	0
Grand Total :	45,247,569	18,284,631	7,668,928	824,262	0	72,025,390

Report Run : 10/10/2023 8:03:25 AM

EDUCATIONAL PLANT FIVE YEAR SURVEY REPORT

College:

3-COLLEGE OF CENTRAL FLORIDA

Survey:

Survey : 3 Version : 2

Status:

Active Pending

Section 4: Expenditures By Fund Source

EDUCATIONAL PLANT FIVE YEAR SURVEY REPORT

College:

3-COLLEGE OF CENTRAL FLORIDA

Survey:

Survey : 3 Version : 2

Status:

Active Pending

FUND EXPENDITURES BY FUND SOURCE

Site : OCALA CAMPUS

Site Number : 1

Fund Name	2022 - 2023	2023 - 2024	2024 - 2025	2025 - 2026	2026 - 2027	5 Year Total
Revenue Flowthrough And Interest	850,000	0	0	0	0	850,000
Bond Proceeds, SBE Capital Outlay Bonds	0	0	0	0	0	0
State General Revenue	0	0	0	0	0	0
Remodeling/Renovation, Maint./Repair, and Site Improvement	28,477,688	0	5,563,766	0	0	34,041,454
Removal Of Asbestos	0	0	0	0	0	0
New Construction	11,517,996	18,284,631	2,105,162	824,262	0	32,732,051
Library, Books and Films	0	0	0	0	0	0
Correction Of Fire Safety Deficiencies	0	0	0	0	0	0
Modification For Physically Handicapped	0	0	0	0	0	0
Correction of Safety-To-Life Deficiencies	101,885	0	0	0	0	101,885
Local Funds	4,300,000	0	0	0	0	4,300,000
Student Capital Fee	0	0	0	0	0	0
Grand Total :	45,247,569	18,284,631	7,668,928	824,262	0	72,025,390

Report Run : 10/10/2023 8:03:25 AM

EDUCATIONAL PLANT FIVE YEAR SURVEY REPORT

College:

3-COLLEGE OF CENTRAL FLORIDA

Survey:

Survey : 3 Version : 2

Status:

Active Pending

Section 5: Capital Outlay Bonds

EDUCATIONAL PLANT FIVE YEAR SURVEY REPORT

College:

3-COLLEGE OF CENTRAL FLORIDA

Survey:

Survey : 3 Version : 2

Status:

Active Pending

EDUCATIONAL PLANT FIVE YEAR SURVEY REPORT

College:

3-COLLEGE OF CENTRAL FLORIDA

Survey:

Survey : 3 Version : 2

Status:

Active Pending

Section 6: COFTE Projections

EDUCATIONAL PLANT FIVE YEAR SURVEY REPORT

College:

3-COLLEGE OF CENTRAL FLORIDA

Survey:

Survey : 3 Version : 2

Status:

Active Pending

COFTE REPORT

COLLEGE : COLLEGE OF CENTRAL FLORIDA**CAMPUS :** OCALA CAMPUS**SURVEY :** 3 **Version :** 2

ITEM	2021 - 2022	2022 - 2023	2023 - 2024	2024 - 2025	2025 - 2026	2026 - 2027
NON-VOCATIONAL FTE						
Annual FTE :	2,637	2,544	2,448	2,350	2,249	2,139
+/- FTE :	0	-367	-359	-343	-310	-273
Adjusted Annual FTE:	2,637	2,177	2,089	2,007	1,939	1,866
VOCATIONAL FTE						
Annual FTE:	1,194	1,152	1,109	1,064	1,018	969
+/- FTE:	0	-47	-42	-21	26	74
Adjusted Annual FTE:	1,194	1,105	1,067	1,043	1,044	1,043
TOTAL CAPITAL OUTLAY FTE PROJECTIONS:	3,831	3,282	3,156	3,050	2,983	2,909

EDUCATIONAL PLANT FIVE YEAR SURVEY REPORT

College:

3-COLLEGE OF CENTRAL FLORIDA

Survey:

Survey : 3 Version : 2

Status:

Active Pending

COFTE REPORT

COLLEGE : COLLEGE OF CENTRAL FLORIDA**CAMPUS :** College Wide**SURVEY :** 3 **Version :** 2

ITEM	2021 - 2022	2022 - 2023	2023 - 2024	2024 - 2025	2025 - 2026	2026 - 2027
NON-VOCATIONAL FTE						
Annual FTE :	3,211	3,098	2,981	2,862	2,738	2,605
+/- FTE :	0	-463	-455	-435	-394	-348
Adjusted Annual FTE:	3,211	2,635	2,526	2,427	2,344	2,257
VOCATIONAL FTE						
Annual FTE:	1,334	1,287	1,238	1,189	1,138	1,083
+/- FTE:	0	-45	-39	-18	32	86
Adjusted Annual FTE:	1,334	1,242	1,199	1,171	1,170	1,169
TOTAL CAPITAL OUTLAY FTE PROJECTIONS:	4,545	3,877	3,725	3,598	3,514	3,426

EDUCATIONAL PLANT FIVE YEAR SURVEY REPORT

College:

3-COLLEGE OF CENTRAL FLORIDA

Survey:

Survey : 3 Version : 2

Status:

Active Pending

Section 7: Summary of Satisfactory Student Stations

EDUCATIONAL PLANT FIVE YEAR SURVEY REPORT

College:

3-COLLEGE OF CENTRAL FLORIDA

Survey:

Survey : 3 Version : 2

Status:

Active Pending

SUMMARY OF SATISFACTORY STUDENT STATIONS

Survey : 3 Version : 2

College Name : COLLEGE OF CENTRAL FLORIDA Date : 10/10/2023 8:04:42 AM
 Site Number : 1
 Site Name : OCALA CAMPUS

SPACE CATEGORY	GENERAL CLASSROOMS	NON-VOCATIONAL LABS	VOCATIONAL LABS
2026 - 2027 Out Year CO-FTE	2,909	1,866	1,043
Utilization Index Reciprocal	0.50	0.25	0.50
Student Stations Generated	1,455	467	522
Recommended Student Stations 2026 - 2027 Out Year CO-FTE	1,575	370	346
Program Facilities List(Under)/Over	121	-97	-176

INVENTORY :
Student Stations :

Existing	1,142	288	174
Remodeling	10	15	60
Renovation	0	0	0
Construction	775	630	90

SURVEY PLAN :

Total Student Stations Planned	1,927	933	324
Utilization Index	2	4	2
COFTE Provided For In Survey Plan	3,854	3,732	648
2026 - 2027 Out Year CO-FTE	2,909	1,866	1,043
COFTE Survey Plan (Under)/Over	945	1,866	-395

Total UnSatisfactory Student Stations : 1,219

EDUCATIONAL PLANT FIVE YEAR SURVEY REPORT

College:

3-COLLEGE OF CENTRAL FLORIDA

Survey:

Survey : 3 Version : 2

Status:

Active Pending

Section 8: Existing Satisfactory Student Stations By Space and Facility

EDUCATIONAL PLANT FIVE YEAR SURVEY REPORT

College:

3-COLLEGE OF CENTRAL FLORIDA

Survey:

Survey : 3 Version : 2

Status:

Active Pending

EXISTING SATISFACTORY STUDENT STATIONS AND SPACE BY FACILITY

College : COLLEGE OF CENTRAL FLORIDA

Survey : 3

Version : 2

Site : OCALA CAMPUS

Site No : 1

FACILITY					STUDENT STATIONS				SQUARE FEET	
Number	Name	Type	Status	Condition	Class room	Non-Voc Ed	Voc Ed	TOTAL	Net	Gross
1	FOUNDERS HALL	Building	Permanent	Satisfactory	0	0	0	0	22,245	28,270
2	SCIENCE & TECHNOLOGY	Building	Permanent	Satisfactory	324	101	0	425	45,796	55,871
3	LEARNING RESOURCES C	Building	Permanent	Satisfactory	29	0	0	29	44,865	47,315
4	FINE ARTS/COMMUNICAT	Building	Permanent	Satisfactory	48	127	0	175	45,969	49,904
5	STUDENT UNION/PAT. C	Building	Permanent	Satisfactory	0	0	0	0	39,052	47,353
6	ALLIED HEALTH	Building	Permanent	Satisfactory	151	0	45	196	22,493	27,167
9	INSTRUCTIONAL CENTER	Building	Permanent	Satisfactory	78	25	15	118	12,995	17,373
10	PLANT OPERATIONS	Building	Permanent	Satisfactory	0	0	0	0	5,743	7,903
11	BUS. SUPPORT/VETERAN	Building	Permanent	Satisfactory	0	0	0	0	3,501	4,308
12	AQUATIC CENTER	Building	Permanent	Remodeling C	0	0	0	0	4,100	4,990
16	PERSONAL SERV. INST.	Building	Permanent	Satisfactory	0	15	0	15	10,091	11,022
18	LEARNING LAB SCH/CHI	Building	Permanent	Satisfactory	0	0	0	0	5,703	6,391
19	HEALTH SCIENCE	Building	Permanent	Satisfactory	263	0	10	273	25,092	26,832
20	UNIVERSITY CENTER	Building	Permanent	Satisfactory	0	0	0	0	0	31,067
23	STORAGE	Building	Permanent	Satisfactory	0	0	0	0	0	9,500
40	CENTURY CENTER	Building	Permanent	Satisfactory	249	20	104	373	56,432	61,925
51	E. CAMPUS CHILLER PL	Building	Permanent	Satisfactory	0	0	0	0	5,063	5,803
53	ADT ATHLETIC DEV TRA	Building	Permanent	Satisfactory	0	0	0	0	839	918
54	ADT WEIGHT ROOM	Building	Permanent	Satisfactory	0	0	0	0	2,023	2,240
55	PUBLIC SAFETY	Building	Permanent	Satisfactory	0	0	0	0	1,558	1,853
56	COMMUNICATION SYSTEM	Building	Permanent	Satisfactory	0	0	0	0	624	1,036
57	CENTRAL RECEIVING	Building	Permanent	Satisfactory	0	0	0	0	12,250	14,600
58	ELECTRICAL/PAINT SHO	Building	Permanent	Satisfactory	0	0	0	0	2,808	3,078
59	WAREHOUSE	Building	Permanent	Satisfactory	0	0	0	0	1,930	2,168
60	TENNIS COURT SUPPORT	Building	Permanent	Satisfactory	0	0	0	0	679	1,020
61	TENNIS COURTS	Athletic Area	Permanent	Satisfactory	0	0	0	0	0	58,320

EDUCATIONAL PLANT FIVE YEAR SURVEY REPORT

College:

3-COLLEGE OF CENTRAL FLORIDA

Survey:

Survey : 3 Version : 2

Status:

Active Pending

62	HANDBALL COURTS	Building	Permanent	Satisfactory	0	0	0	0	357	7,420
63	BASEBALL DIAMD	Athletic Area	Permanent	Satisfactory	0	0	0	0	0	168,720
64	DUGOUT/PRESSBOX	Building	Permanent	Satisfactory	0	0	0	0	4,529	4,865
65	SOFTBALL BUILDING	Building	Permanent	Satisfactory	0	0	0	0	974	1,275
66	WOMEN'S SOFTBALL LCK	Building	Permanent	Satisfactory	0	0	0	0	1,128	2,064
67	BASEBALL BATTING CAG	Building	Permanent	Satisfactory	0	0	0	0	3,103	3,774
68	SOFTBALL BATTING CAG	Building	Permanent	Satisfactory	0	0	0	0	3,058	3,774
69	SOFTBALL FIELD	Athletic Area	Permanent	Satisfactory	0	0	0	0	0	46,414
71	THE WEBBER CENTER	Building	Permanent	Satisfactory	0	0	0	0	8,548	10,554
121	SWIMMING POOL	Outdoor Swimming Pool	Permanent	Satisfactory	0	0	0	0	0	11,840
5000	PARKING LOT #1	Parking Area	Permanent	Satisfactory	0	0	0	0	0	21,836
5001	PARKING LOT #2	Parking Area	Permanent	Satisfactory	0	0	0	0	0	57,592
5002	PARKING LOT #4	Parking Area	Permanent	Satisfactory	0	0	0	0	0	56,786
5003	PARKING LOT #4A	Parking Area	Permanent	Satisfactory	0	0	0	0	0	106,023
5004	PARKING LOT #5A	Parking Area	Permanent	Satisfactory	0	0	0	0	0	33,354
5005	PARKING LOT #5B	Parking Area	Permanent	Satisfactory	0	0	0	0	0	39,745
5006	PARKING LOT #6	Parking Area	Permanent	Satisfactory	0	0	0	0	0	40,618
5007	PARKING LOT #8	Parking Area	Permanent	Satisfactory	0	0	0	0	0	21,552
5008	PARKING LOT #9	Parking Area	Permanent	Satisfactory	0	0	0	0	0	71,162
5009	PARKING LOT #10	Parking Area	Permanent	Satisfactory	0	0	0	0	0	25,665
5010	PARKING LOT #12	Parking Area	Permanent	Satisfactory	0	0	0	0	0	52,044
5012	PARKING LOT #15	Parking Area	Permanent	Satisfactory	0	0	0	0	0	57,736
5013	PARKING LOT #16	Parking Area	Permanent	Satisfactory	0	0	0	0	0	16,315
5015	PARKING LOT #18	Parking Area	Permanent	Satisfactory	0	0	0	0	0	30,187
5016	PARKING LOT #19	Parking Area	Permanent	Satisfactory	0	0	0	0	0	59,611
5017	PARKING LOT #19A	Parking Area	Permanent	Satisfactory	0	0	0	0	0	60,110
5018	PARKING LOT #24	Parking Area	Permanent	Satisfactory	0	0	0	0	0	77,982
5019	PARKING LOT #31	Parking Area	Permanent	Satisfactory	0	0	0	0	0	47,311
5020	PARKING LOT #32	Parking Area	Permanent	Satisfactory	0	0	0	0	0	112,823
5022	PARKING LOT #33	Parking Area	Permanent	Satisfactory	0	0	0	0	0	71,388

EDUCATIONAL PLANT FIVE YEAR SURVEY REPORT

College:

3-COLLEGE OF CENTRAL FLORIDA

Survey:

Survey : 3 Version : 2

Status:

Active Pending

5023	PARKING LOT #40A	Parking Area	Permanent	Satisfactory	0	0	0	0	0	50,488
5024	PARKING LOT #40B	Parking Area	Permanent	Satisfactory	0	0	0	0	0	36,721
5025	PARKING LOT #41	Parking Area	Permanent	Satisfactory	0	0	0	0	0	76,244
5026	PARKING LOT #42	Parking Area	Permanent	Satisfactory	0	0	0	0	0	29,507
5027	PARKING LOT #71	Parking Area	Permanent	Satisfactory	0	0	0	0	0	36,668
5085	PUMPHOUSE(PPOOL AREA)	Building	Permanent	Satisfactory	0	0	0	0	308	322
5087	PUMPHOUSE (NE CORNR)	Building	Permanent	Satisfactory	0	0	0	0	442	471
OCALA CAMPUS Totals :					1,142	288	174	1,604	394,298	2,079,188
Total UnSatisfactory NSF :					108,581					
Total UnSatisfactory Student Stations :					1,219					
College-wide Facility Totals :					1,142	288	174	1,604	394,298	2,079,188

EDUCATIONAL PLANT FIVE YEAR SURVEY REPORT

College:

3-COLLEGE OF CENTRAL FLORIDA

Survey:

Survey : 3 Version : 2

Status:

Active Pending

Section 9: Summary of Existing And Recommended Square Footage

EDUCATIONAL PLANT FIVE YEAR SURVEY REPORT

College:

3-COLLEGE OF CENTRAL FLORIDA

Survey:

Survey : 3 Version : 2

Status:

Active Pending

SUMMARY OF EXISTING AND RECOMMENDED SQUARE FOOTAGE

Survey : 3 Version : 2

College Name : COLLEGE OF CENTRAL FLORIDA

Date : 10/10/2023 8:04:42 AM

Site Number : 1

Admin Site : NO

Site Name : OCALA CAMPUS

SPACE CATEGORY	2026 - 2027 SPACE ALLOCATION	EXISTING INVENTORY SPACE	SPACE DEFICIT OR SURPLUS	CONSTRUCTION NSF	REMODEL NSF	SURVEY RECOMMENDED SPACE
Instructional Spaces :						
Classrooms	39,375	32,130	-7,245	21,700	1,265	55,095
Non-Vocational Spaces	20,540	26,474	5,934	47,905	1,500	75,879
Vocational Spaces	27,647	27,797	150	13,940	9,760	51,497
Physical Education	24,545	14,018	-10,527	0	3,797	17,815
Subtotal	112,107	100,419	-11,688	83,545	16,322	200,286
Academic Support:						
Library	33,099	21,949	-11,150	0	0	21,949
Audiovisual	4,378	525	-3,853	0	0	525
Auditorium/Exhibition	12,727	23,187	10,460	0	0	23,187
Student Services	21,818	9,844	-11,974	0	0	9,844
Subtotal	72,022	55,505	-16,517	0	0	55,505
Institutional Support:						
Office	36,363	68,387	32,025	0	0	68,387
Support Services	11,025	47,687	36,662	0	0	47,687
Custodial Services	3,200	3,036	-164	0	0	3,036
Sanitation:						
*Student Restrooms	4,364	9,147	4,783	0	0	9,147
*Staff/Public Restrooms	727	1,489	762	0	0	1,489
Subtotal	55,678	129,746	74,068	0	0	129,746
*HVAC /Mech/Sanitation	14,388	33,829	19,441	0	0	33,829
Circulation	86,426	83,555	2,871	0	0	83,555
Total Net Square Feet	340,621	403,054	87,508	83,545	16,322	502,921

Leased / Rented NSF not in Survey : 146,124

EDUCATIONAL PLANT FIVE YEAR SURVEY REPORT

College:

3-COLLEGE OF CENTRAL FLORIDA

Survey:

Survey : 3 Version : 2

Status:Active Pending

Total NSF for all Sites : 285,670

Leased / Rented NSF not in Survey : 146,124

* : In College Surveys, New Construction for Restroom space is included in HVAC/Mech/Sanitation.

EDUCATIONAL PLANT FIVE YEAR SURVEY REPORT

College:

3-COLLEGE OF CENTRAL FLORIDA

Survey:

Survey : 3 Version : 2

Status:

Active Pending

Section 10: Facility Lists

EDUCATIONAL PLANT FIVE YEAR SURVEY REPORT

College:

3-COLLEGE OF CENTRAL FLORIDA

Survey:

Survey : 3 Version : 2

Status:

Active Pending

PROGRAM FACILITES LIST

College : COLLEGE OF CENTRAL FLORIDA

OUT Year: 5 - 6

Survey : 3

Version: 2

Site: OCALA CAMPUS

Site No: 1

Stations Allowed

Current Stations

Classroom FTE: 2,909

1,454

0

Non-Voc FTE: 1,866

466

370

Vocational FTE: 1,043

521

346

ICS Code	Description	Stations Per Space	SQ/FT Per Station	SQ/FT Per Space	Spaces	Total SQ Foot	Total Stations
	Storage, Material			75	63	4,725	0
				75	63	4,725	0
	Storage, Material			150	2	300	0
	Storage, Project			275	2	550	0
				425	4	850	0
	Storage, Material			100	1	100	0
	Storage, Project			200	1	200	0
				300	2	300	0
	Storage, Material			100	1	100	0
	Storage, Project			200	1	200	0
				300	2	300	0
	Storage, Material			150	2	300	0
	Storage, Project			200	2	400	0
				350	4	700	0
	Kiln			60	3	180	0
	Storage, Material			200	3	600	0
				260	6	780	0
	Ensemble			300	2	600	0
	Practice, Music 3@60sf			180	2	360	0
	Reference			150	2	300	0
	Storage, Instrument			400	2	800	0

EDUCATIONAL PLANT FIVE YEAR SURVEY REPORT

College:

3-COLLEGE OF CENTRAL FLORIDA

Survey:

Survey : 3 Version : 2

Status:

Active Pending

Storage, Robe	60	2	120	0
Storage, Uniform	60	2	120	0
	1,150	12	2,300	0
Laser Alignment Tunnel	300	1	300	0
Storage, Material	250	1	250	0
Testing	300	1	300	0
	850	3	850	0
Conference	600	1	600	0
Storage, Material	400	1	400	0
Testing	900	1	900	0
	1,900	3	1,900	0
Classroom,Related Instruct.	525	1	525	0
Storage, Material	800	1	800	0
Technical Laboratory	900	1	900	0
	2,225	3	2,225	0
Classroom,Related Instruct.	525	1	525	0
Storage, Material	500	1	500	0
Technical Laboratory	900	1	900	0
	1,925	3	1,925	0
Storage, Material	150	1	150	0
	150	1	150	0
Classroom,Related Instruct.	525	1	525	0
Storage, Material	500	1	500	0
Telemetry Operations	1,000	1	1,000	0
	2,025	3	2,025	0
Classroom,Related Instruct.	525	3	1,575	0
Locker, Faculty	90	3	270	0
Locker, Student	350	3	1,050	0
Reference	350	3	1,050	0
Storage, Material	400	3	1,200	0
	1,715	15	5,145	0
Hydrotherapy	550	1	550	0
Lockers, Showers, & Toilets - Faculty	120	1	120	0

EDUCATIONAL PLANT FIVE YEAR SURVEY REPORT

College:

3-COLLEGE OF CENTRAL FLORIDA

Survey:

Survey : 3 Version : 2

Status:

Active Pending

Lockers, Showers, & Toilets - Student	225	1	225	0		
Storage, Material	250	1	250	0		
Toilet, Patient	75	1	75	0		
	1,220	5	1,220	0		
Classroom,Related Instruct.	525	1	525	0		
Maintenance	200	1	200	0		
Storage, Material	400	1	400	0		
	1,125	3	1,125	0		
Scrub Area	100	1	100	0		
Sterilization	80	1	80	0		
Storage, Material	350	1	350	0		
Surgical Operations	1,200	1	1,200	0		
	1,730	4	1,730	0		
Storage, Material	100	1	100	0		
	100	1	100	0		
Classroom,Related Instruct.	525	5	2,625	0		
Storage, Material	100	5	500	0		
	625	10	3,125	0		
Storage, Material	150	1	150	0		
	150	1	150	0		
Classroom,Related Instruct.	525	1	525	0		
Storage, Material	100	1	100	0		
	625	2	625	0		
Classroom,Related Instruct.	525	1	525	0		
Courtroom	550	1	550	0		
Darkroom	350	1	350	0		
Photography Lab	500	1	500	0		
Reference	250	1	250	0		
Technical Laboratory	900	1	900	0		
	3,075	6	3,075	0		
1.XX.XXXXX Classroom	25	25	625	63	39,375	1,575
	625	63	39,375	1,575		

EDUCATIONAL PLANT FIVE YEAR SURVEY REPORT

College:

3-COLLEGE OF CENTRAL FLORIDA

Survey:

Survey : 3 Version : 2

Status:

Active Pending

1.11.04XXX	Biological Sciences	21	55	1,155	2	2,310	42
				1,155	2	2,310	42
1.11.09XXX	Engineering	25	80	2,000	1	2,000	25
				2,000	1	2,000	25
1.11.12XXX	Health Professions	15	80	1,200	1	1,200	15
				1,200	1	1,200	15
1.11.19XXX	Physical Sciences	19	55	1,045	2	2,090	38
				1,045	2	2,090	38
1.12.1002X	Art	18	50	900	3	2,700	54
				900	3	2,700	54
1.12.10041	Music(Choral or Band)	38	35	1,330	2	2,660	76
				1,330	2	2,660	76
1.31.2XXXX	Adult General & Preparatory	20	47	940	1	940	20
				940	1	940	20
1.32.2XXXX	Adult General & Preparatory	20	47	940	1	940	20
				940	1	940	20
1.23.0914X	Cardiopulmonary Technology	15	167	2,505	1	2,505	15
				2,505	1	2,505	15
1.23.0504X	Diagnostic Medical Sonography	15	80	1,200	1	1,200	15
				1,200	1	1,200	15
1.23.0902X	Electrocardiograph Tech.	15	62	930	1	930	15
				930	1	930	15
1.23.0907X	Emergency Medical Tech.	15	88	1,320	1	1,320	15
				1,320	1	1,320	15
1.23.0301X	Nursing (RN)	7	158	1,106	3	3,318	21
				1,106	3	3,318	21
1.23.04021	Physical Therapy Assistant	15	80	1,200	3	3,600	45
				1,200	3	3,600	45

EDUCATIONAL PLANT FIVE YEAR SURVEY REPORT

College:

3-COLLEGE OF CENTRAL FLORIDA

Survey:

Survey : 3 Version : 2

Status:

Active Pending

1.23.09031	Respiratory Therapist	15	80	1,200	1	1,200	15
				1,200	1	1,200	15
1.23.0305X	Surgical Technology	15	100	1,500	1	1,500	15
				1,500	1	1,500	15
1.25.01XXX	Accounting & Computing	19	56	1,064	1	1,064	19
				1,064	1	1,064	19
1.25.02XXX	Business Data Processing	18	63	1,134	5	5,670	90
				1,134	5	5,670	90
1.26.25XXX	Engineering Related Technology	15	27	405	1	405	15
				405	1	405	15
1.26.25061	Safety Engineering Technology	15	57	855	1	855	15
				855	1	855	15
1.27.02012	Criminal Justice Technology	15	80	1,200	1	1,200	15
				1,200	1	1,200	15
1.11.1203X	Nursing (Four Year Programs)	20	80	1,600	3	4,800	60
				1,600	3	4,800	60
1.16.0701X	Computer and Information Science, General	20	45	900	1	900	20
				900	1	900	20
1.23.0402X	Physical Therapy	7	80	560	3	1,680	21
				560	3	1,680	21
1.23.05XXX	Radiologic	15	80	1,200	1	1,200	15
				1,200	1	1,200	15
OCALA CAMPUS Totals :				52,314	261	122,887	2,291
Report Totals :				52,314	261	122,887	2,291

EDUCATIONAL PLANT FIVE YEAR SURVEY REPORT

College:

3-COLLEGE OF CENTRAL FLORIDA

Survey:

Survey : 3 Version : 2

Status:

Active Pending

EDUCATIONAL PLANT FIVE YEAR SURVEY REPORT

College:

3-COLLEGE OF CENTRAL FLORIDA

Survey:

Survey : 3 Version : 2

Status:

Active Pending

Section 11: Recommendation Details

EDUCATIONAL PLANT FIVE YEAR SURVEY REPORT

College:

3-COLLEGE OF CENTRAL FLORIDA

Survey:

Survey : 3 Version : 2

Status:

Active Pending

COLLEGE WIDE RECOMMENDATIONS

NUMBER	DESCRIPTION	ESTIMATED COST
SR.01	Correct deficiencies relating to safety to life, health, and sanitation as identified in the comprehensive Safety Inspection Report pursuant to §4.4(1) and §5(1) SREF.	1,250,000
SR.02	Necessary modifications for the physically disabled in existing buildings recommended for continued use as provided for in §255.21 F.S.	850,000
SR.03	Replacement of roofs at existing facilities as provided in §1.2(55) SREF and §423.12 Florida Building Code.	850,000
SR.04	Replace or purchase of equipment for existing facilities pursuant to §1.2(55) SREF.	2,500,000
SR.05	Provide for sanitation facilities for students, staff, and the public pursuant to §5(1) SREF and §423.2 Florida Building Code.	105,000
SR.06	Provide for custodial facilities pursuant to §423.20 Florida Building Code.	300,000
1	1	0
Total :		5,855,000

COMMUNITY COLLEGE RECOMMENDATION DETAIL REPORT

Site No: 1

Site Name: OCALA CAMPUS

SITE RECOMMENDATIONS

NUMBER	DESCRIPTION	ESTIMATED COST
1.079	Remodel of 25,204 GSF Building 42 (Classrooms, Teaching labs, Library, Vocational Labs, Offices, Auditorium/exhibits, Instructional Media, Gymnasium, Student Services, Support Services related to Radiography Technology, Physical Therapy Assisting, and Teacher Educator programs).	7,331,340
1.080	Remodel of 25,204 GSF Building 42 related project costs (Professional Fees and Services, Testing/Surveys, Permits/Fees, Misc., movable equipment/furnishings).	2,203,068
1.081	Building 42 Site Preparation: Removal and disposition of ground as required for remodel, and regrading for building site work.	25,000
1.082	Building 42 Landscape/Irrigation: Irrigation, materials, supplies, labor to install, Landscaping materials, plants, trees, labor to install.	50,000
1.083	Building 42 Plaza/Walks: Student seating plazas and 25x5' walkways and expanded outdoor seating/storage areas connecting the existing facility to the parking lot.	15,000
1.084	Building 42 Roadway improvements: Curbing changes, asphalt to loop road.	50,000
1.085	Building 42 Parking Spaces: Construction of 50 parking spaces with required site lighting (8 LED fixtures w/ 35' concrete poles).	140,000
1.086	Building 42 Telecommunication: Run 425 lf of underground fiber-optic communication cable.	31,500
1.087	Building 42 Electrical Service: Tie into existing loop and provide above-ground vaults as required for remodel work.	25,000
1.088	Building 42 Water Distribution: Upgrade 8" water main and BFP as needed to support the building fire sprinkler system.	40,000
1.089	Building 42 Sanitary sewer system: Upgrade 10" PVC piping system, and required man holes per remodeled system design.	40,885
1.090	Building 42 HVAC system: Tie into East Campus Chiller Plant with associated pumps, air handlers, and associated controls, and electrical service, to support the remodeled facility.	175,000
1.091	Building 42 Stormwater system: Construction of drainage retention pond with related inlets and piping to support the building, parking lot and walkway construction.	68,995
1.092	Building 42 Other: Access control systems & lead lining for radiography equipment.	200,000
1.093	Remodel of 31,067 GSF Building 20 Advanced Technical Center (ATC) (Classrooms, Teaching labs, Support and Student Services related to Engineering Technology, Network and Cybersecurity and	9,036,614

EDUCATIONAL PLANT FIVE YEAR SURVEY REPORT

College:

3-COLLEGE OF CENTRAL FLORIDA

Survey:

Survey : 3 Version : 2

Status:

Active Pending

Soldering programs).

1.094	Remodel of 31,067 GSF Building 20 Advanced Technical Center (ATC) related project costs (Professional Fees and Services, Testing/Surveys, Permits/Fees, Misc., movable equipment/furnishings).	2,715,502
1.095	Building 20 (ATC) Site Preparation	25,000
1.096	Building 20 (ATC) Landscape/Irrigation	50,000
1.097	Building 20 (ATC) Plaza/Walks	15,000
1.098	Building 20 (ATC) Roadway Improvements	50,000
1.099	Building 20 (ATC) Parking Spaces	140,000
1.100	Building 20 (ATC) Telecommunication	31,500
1.101	Building 20 (ATC) Electrical Service	25,000
1.102	Building 20 (ATC) Water Distribution	40,000
1.103	Building 20 (ATC) Sanitary Sewer System	40,885
1.104	Building 20 (ATC) Chilled Water System	125,000
1.105	Building 20 (ATC) Storm Water System	68,995
1.106	Building 20 (ATC) Access Control System	78,885

OCALA CAMPUS Total : 22,838,169

NEW CONSTRUCTION / REMODEL / RENOVATE

NUMBER	DESCRIPTION	ESTIMATED COST
1.041	New Construction: Adding Non-Vocational Labs (300 SS), (25200 NSF), (35794 GSF); Vocational Labs (75 SS), (9665 NSF), (13729 GSF); Health Professions (21200 NSF), Physical Therapy (2000 NSF), Nursing (RN) (5665 NSF), Radiologic (2000 NSF), Nursing (Four Year Programs) (4000 NSF)	22,037,290
1.042	New Construction: Adding Classrooms (775 SS), (21700 NSF), (30823 GSF); Classroom (21700 NSF)	13,715,790
1.043	New Construction: Adding Non-Vocational Labs (90 SS), (4050 NSF), (5753 GSF); Computer and Information Science, General (4050 NSF)	2,559,640
1.044	New Construction: Adding Non-Vocational Labs (120 SS), (7875 NSF), (11186 GSF); Biological Sciences (7875 NSF)	4,977,325
1.045	New Construction: Adding Non-Vocational Labs (80 SS), (5100 NSF), (7244 GSF); Physical Sciences (5100 NSF)	3,223,580
1.046	New Construction: Adding Non-Vocational Labs (20 SS), (2840 NSF), (4034 GSF); Adult Secondary (2840 NSF)	1,794,685
1.047	New Construction: Adding Non-Vocational Labs (20 SS), (2840 NSF), (4034 GSF); Adult Secondary (2840 NSF)	1,794,685
1.048	New Construction: Adding Vocational Labs (15 SS), (4275 NSF), (6072 GSF); Criminal Justice Technology (4275 NSF)	2,702,040
1.049	Remodeling Building Number - 12, Building Name - AQUATIC CENTER : Adding Physical Education (3797 NSF), (5393 GSF); Physical Education (3797 NSF) and Removing (0 SS), (4100 NSF) Room 100 (622 NSF), Room 100A (43 NSF), Room 100B (272 NSF), Room 100C (134 NSF), Room 100D (28 NSF), Room 101 (163 NSF), Room 101A (27 NSF), Room 102 (103 NSF), Room 103 (1044 NSF), Room 104 (1045 NSF), Room 150 (595 NSF), Room 150A (24 NSF)	912,250
1.050	Remodeling Building Number - 19, Building Name - HEALTH SCIENCE : Adding Classrooms (10 SS), (1265 NSF), (1797 GSF); Classroom (1265 NSF, 10 SSC) and Removing (3 SS), (1785 NSF) Room 108C (700 NSF), Room 108 (1085 NSF)	397,162
1.051	Remodeling Building Number - 6, Building Name - GYMNASIUM : Adding Non-Vocational Labs (15 SS), (1500 NSF), (2131 GSF); Vocational Labs (60 SS), (9760 NSF), (13863 GSF); Respiratory Therapist (2325 NSF, 15 SSC), Surgical Technology (3230 NSF, 15 SSC), Electrcardiograph Tech. (1080 NSF, 15 SSC), Diagnostic Medical Sonography (3125 NSF, 15 SSC),	4,837,372

EDUCATIONAL PLANT FIVE YEAR SURVEY REPORT

College:

3-COLLEGE OF CENTRAL FLORIDA

Survey:

Survey : 3 Version : 2

Status:

Active Pending

Health Professions (1500 NSF, 15 SSC) and Removing (0 SS), (21741 NSF) Room 100 (1012 NSF), Room 101 (13168 NSF), Room 102 (136 NSF), Room 103 (378 NSF), Room 103A (220 NSF), Room 106 (220 NSF), Room 106A (221 NSF), Room 107 (226 NSF), Room 108 (447 NSF), Room 109 (70 NSF), Room 109A (109 NSF), Room 109B (400 NSF), Room 109C (84 NSF), Room 110 (225 NSF), Room 110A (220 NSF), Room 111 (360 NSF), Room 111A (382 NSF), Room 111B (218 NSF), Room 111C (55 NSF), Room 111D (88 NSF), Room 112 (872 NSF), Room 112A (145 NSF), Room 113 (111 NSF), Room 113A (60 NSF), Room 114 (702 NSF), Room 115 (335 NSF), Room 115A (50 NSF), Room 116 (692 NSF), Room 117 (499 NSF), Room 117A (36 NSF)

1.052 Renovating Building Number - 19, Building Name - HEALTH SCIENCE (230 SS), (24262 NSF) 3,598,863

Apply Painting, Floor Cover, Electrical, Plumbing, Windows, Lighting, Restrooms, HVAC Systems, Bell/Fire Alarm Systems, Retrofit for Technology to Room 100 (3602 NSF), Room 100A (76 NSF), Room 102 (48 NSF), Room 102A (91 NSF), Room 102B (139 NSF), Room 102C (12 NSF), Room 102D (96 NSF), Room 102E (91 NSF), Room 102F (96 NSF), Room 102G (96 NSF), Room 102H (12 NSF), Room 103 (182 NSF), Room 103A (108 NSF), Room 103B (52 NSF), Room 104A (210 NSF), Room 104B (105 NSF), Room 104C (102 NSF), Room 104D (102 NSF), Room 104E (100 NSF), Room 104F (100 NSF), Room 105 (75 NSF), Room 108A (106 NSF), Room 109 (320 NSF), Room 109A (240 NSF), Room 111 (279 NSF), Room 111A (114 NSF), Room 111B (216 NSF), Room 111C (97 NSF), Room 110A (104 NSF), Room 112A (109 NSF), Room 115A (98 NSF), Room 115B (97 NSF), Room 115C (100 NSF), Room 115D (101 NSF), Room 115E (99 NSF), Room 115F (100 NSF), Room 117 (424 NSF), Room 118 (1787 NSF), Room 114 (1335 NSF), Room 112B (168 NSF), Room 110B (165 NSF), Room 112 (1337 NSF), Room 110 (1081 NSF), Room 108B (165 NSF), Room 106 (1107 NSF), Room 106A (50 NSF), Room 106B (350 NSF), Room 101 (1281 NSF), Room 101A (318 NSF), Room 116 (717 NSF), Room 118A (90 NSF), Room 119 (1940 NSF), Room 120 (1879 NSF), Room 120A (503 NSF), Room 120B (105 NSF), Room 108C (700 NSF), Room 108 (1085 NSF) Renovation Description:

1.053 Renovating Building Number - 1, Building Name - FOUNDERS HALL (0 SS), (21041 NSF) 3,121,081

Apply Painting, Floor Cover, Electrical, Plumbing, Windows, Lighting, Restrooms, HVAC Systems, Bell/Fire Alarm Systems, Retrofit for Technology, Other to Room 100 (3700 NSF), Room 100A (211 NSF), Room 100B (18 NSF), Room 100C (216 NSF), Room 100D (51 NSF), Room 100E (51 NSF), Room 100F (84 NSF), Room 100G (37 NSF), Room 101 (338 NSF), Room 101A (142 NSF), Room 101B (136 NSF), Room 101C (375 NSF), Room 101D (343 NSF), Room 102 (343 NSF), Room 102A (280 NSF), Room 104 (467 NSF), Room 104A (68 NSF), Room 104B (199 NSF), Room 104C (159 NSF), Room 104D (158 NSF), Room 104E (178 NSF), Room 104F (171 NSF), Room 104G (70 NSF), Room 105 (270 NSF), Room 106 (304 NSF), Room 106A (78 NSF), Room 107 (280 NSF), Room 107A (407 NSF), Room 107B (375 NSF), Room 107C (171 NSF), Room 107D (167 NSF), Room 108 (430 NSF), Room 108A (159 NSF), Room 108B (159 NSF), Room 108C (117 NSF), Room 108D (220 NSF), Room 108E (65 NSF), Room 109 (166 NSF), Room 109A (170 NSF), Room 110 (1550 NSF), Room 110A (183 NSF), Room 111 (392 NSF), Room 111A (38 NSF), Room 112 (669 NSF), Room 112A (310 NSF), Room 112B (306 NSF), Room 112C (309 NSF), Room 112D (257 NSF), Room 112E (90 NSF), Room 112F (100 NSF), Room 112G (105 NSF), Room 112H (133 NSF), Room 112J (185 NSF), Room 112K (173 NSF), Room 112L (129 NSF), Room 112M (119 NSF), Room 112N (174 NSF), Room 112P (143 NSF), Room 200 (1364 NSF), Room 200A (176 NSF), Room 200B (18 NSF), Room 200C (133 NSF), Room 201 (437 NSF), Room 202 (234 NSF), Room 203 (388 NSF), Room 203A (235 NSF), Room 203B (77 NSF), Room 204 (436 NSF), Room 205 (180 NSF), Room 206 (135 NSF), Room 207 (172 NSF), Room 208 (358 NSF) Renovation Description: Renovating Building Number - 1, Building Name - FOUNDERS HALL (0 SS), (21285 NSF) Apply Painting, Floor Cover, Electrical, Plumbing, Windows, Lighting, HVAC Systems, Bell/Fire Alarm Systems, Retrofit for Technology, Other to Room 104B (199 NSF), Room 104C (159 NSF), Room 104D (158 NSF), Room 104E (178 NSF), Room 104F (171 NSF), Room 104G (70 NSF), Room 105 (270 NSF), Room 106 (304 NSF), Room 106A (78 NSF), Room 107 (280 NSF), Room 107A (407 NSF), Room 107B (375 NSF), Room 107C (171 NSF), Room 107D (167 NSF), Room 108 (430 NSF), Room 108A (159 NSF), Room 108B (159 NSF), Room 108C (117 NSF), Room 108D (220 NSF), Room 108E (65 NSF), Room 109 (166 NSF), Room 109A (170 NSF), Room 110 (1550 NSF), Room 110A (183 NSF), Room 111 (392 NSF), Room 111A (38 NSF), Room 112 (669 NSF), Room 112A (310 NSF), Room 112B (306 NSF), Room 112C (309 NSF), Room 112D (257 NSF), Room 112E (90 NSF), Room 112F (100 NSF), Room 112G (105 NSF), Room 112H (133 NSF), Room 112J (185 NSF), Room 112K (173 NSF), Room 112L (129 NSF), Room 112M (119 NSF), Room 112N (174 NSF), Room 112P (143 NSF), Room 150 (328 NSF), Room 200 (1364 NSF), Room 200A (176 NSF), Room 200B (18 NSF), Room 200C (133 NSF), Room 201 (437 NSF), Room 202 (234 NSF), Room 203 (388 NSF), Room 203A (235 NSF), Room 203B (77 NSF), Room 204 (436 NSF), Room 205 (180 NSF), Room 206 (135 NSF), Room 207 (172 NSF), Room 208 (358 NSF), Room 100 (3700 NSF), Room 100A (211 NSF), Room 100B (18 NSF), Room 100C (216 NSF), Room 100D (51 NSF), Room 100E (51 NSF), Room 100G (37 NSF), Room 101 (338 NSF), Room 101A (142 NSF), Room 101B (136 NSF), Room 101C (375 NSF), Room 101D (343 NSF), Room 102 (343 NSF), Room 102A (280 NSF), Room 104 (467 NSF), Room 104A (68 NSF)

EDUCATIONAL PLANT FIVE YEAR SURVEY REPORT

College:

3-COLLEGE OF CENTRAL FLORIDA

Survey:

Survey : 3 Version : 2

Status:

Active Pending

Renovating Building Number - 1, Building Name - FOUNDERS HALL (0 SS), (21285 NSF) Apply Painting, Floor Cover, Electrical, Plumbing, Windows, Lighting, HVAC Systems, Bell/Fire Alarm Systems, Retrofit for Technology, Other to Room 104B (199 NSF), Room 104C (159 NSF), Room 104D (158 NSF), Room 104E (178 NSF), Room 104F (171 NSF), Room 104G (70 NSF), Room 105 (270 NSF), Room 106 (304 NSF), Room 106A (78 NSF), Room 107 (280 NSF), Room 107A (407 NSF), Room 107B (375 NSF), Room 107C (171 NSF), Room 107D (167 NSF), Room 108 (430 NSF), Room 108A (159 NSF), Room 108B (159 NSF), Room 108C (117 NSF), Room 108D (220 NSF), Room 108E (65 NSF), Room 109 (166 NSF), Room 109A (170 NSF), Room 110 (1550 NSF), Room 110A (183 NSF), Room 111 (392 NSF), Room 111A (38 NSF), Room 112 (669 NSF), Room 112A (310 NSF), Room 112B (306 NSF), Room 112C (309 NSF), Room 112D (257 NSF), Room 112E (90 NSF), Room 112F (100 NSF), Room 112G (105 NSF), Room 112H (133 NSF), Room 112J (185 NSF), Room 112K (173 NSF), Room 112L (129 NSF), Room 112M (119 NSF), Room 112N (174 NSF), Room 112P (143 NSF), Room 150 (328 NSF), Room 200 (1364 NSF), Room 200A (176 NSF), Room 200B (18 NSF), Room 200C (133 NSF), Room 201 (437 NSF), Room 202 (234 NSF), Room 203 (388 NSF), Room 203A (235 NSF), Room 203B (77 NSF), Room 204 (436 NSF), Room 205 (180 NSF), Room 206 (135 NSF), Room 207 (172 NSF), Room 208 (358 NSF), Room 100 (3700 NSF), Room 100A (211 NSF), Room 100B (18 NSF), Room 100C (216 NSF), Room 100D (51 NSF), Room 100E (51 NSF), Room 100G (37 NSF), Room 101 (338 NSF), Room 101A (142 NSF), Room 101B (136 NSF), Room 101C (375 NSF), Room 101D (343 NSF), Room 102 (343 NSF), Room 102A (280 NSF), Room 104 (467 NSF), Room 104A (68 NSF)

1.054

Renovating Building Number - 2, Building Name - SCIENCE & TECHNOLOGY (425 SS), (42578 NSF) Apply Painting, Floor Cover, Electrical, Plumbing, Windows, Lighting, Restrooms, HVAC Systems, Bell/Fire Alarm Systems, Retrofit for Technology, Other to Room 100 (4852 NSF), Room 102 (750 NSF), Room 103 (130 NSF), Room 104 (608 NSF), Room 105 (1892 NSF), Room 105A (120 NSF), Room 105B (120 NSF), Room 105C (126 NSF), Room 105D (272 NSF), Room 106 (995 NSF), Room 106A (709 NSF), Room 107 (383 NSF), Room 107A (145 NSF), Room 108 (728 NSF), Room 112 (106 NSF), Room 115 (528 NSF), Room 115A (78 NSF), Room 115B (78 NSF), Room 115C (95 NSF), Room 124 (236 NSF), Room 124A (244 NSF), Room 190 (42 NSF), Room 191 (56 NSF), Room 193 (39 NSF), Room 200 (3930 NSF), Room 200A (86 NSF), Room 203 (130 NSF), Room 216 (322 NSF), Room 217A (116 NSF), Room 217B (116 NSF), Room 217C (116 NSF), Room 217D (100 NSF), Room 217E (104 NSF), Room 217F (104 NSF), Room 217G (104 NSF), Room 217H (112 NSF), Room 218A (113 NSF), Room 218B (113 NSF), Room 218C (113 NSF), Room 218D (113 NSF), Room 218E (113 NSF), Room 218F (113 NSF), Room 219A (113 NSF), Room 219B (113 NSF), Room 219C (113 NSF), Room 219D (113 NSF), Room 219E (113 NSF), Room 219F (113 NSF), Room 220A (112 NSF), Room 220B (114 NSF), Room 220C (99 NSF), Room 220D (104 NSF), Room 220E (104 NSF), Room 220F (104 NSF), Room 220G (115 NSF), Room 220H (105 NSF), Room 220I (312 NSF), Room 224 (56 NSF), Room 205 (282 NSF), Room 205A (165 NSF), Room 205B (164 NSF), Room 205C (208 NSF), Room 206A (78 NSF), Room 207 (615 NSF), Room 211 (340 NSF), Room 211A (268 NSF), Room 211B (74 NSF), Room 211C (77 NSF), Room 211D (234 NSF), Room 212 (116 NSF), Room 214 (424 NSF), Room 214A (40 NSF), Room 209 (525 NSF), Room 209A (72 NSF), Room 210 (980 NSF), Room 210A (75 NSF), Room 215 (680 NSF), Room 215A (84 NSF), Room 208 (926 NSF), Room 208A (75 NSF), Room 204 (382 NSF), Room 204A (75 NSF), Room 118C (75 NSF), Room 119 (832 NSF), Room 119A (75 NSF), Room 120 (825 NSF), Room 120A (90 NSF), Room 121 (850 NSF), Room 121A (75 NSF), Room 116 (525 NSF), Room 116A (84 NSF), Room 117 (687 NSF), Room 117A (75 NSF), Room 118A (634 NSF), Room 114 (836 NSF), Room 114A (75 NSF), Room 126A (885 NSF), Room 126B (181 NSF), Room 126 (1384 NSF), Room 128 (1159 NSF), Room 127 (1008 NSF), Room 127D (158 NSF), Room 118B (260 NSF), Room 123 (991 NSF), Room 123A (267 NSF), Room 123B (170 NSF), Room 125 (1020 NSF), Room 125A (183 NSF), Room 125B (174 NSF), Room 125C (174 NSF), Room 125D (158 NSF), Room 206 (456 NSF) Renovation Description: Renovating Building Number - 2, Building Name - SCIENCE & TECHNOLOGY (425 SS), (44314 NSF) Apply Painting, Floor Cover, Electrical, Plumbing, Windows, Lighting, HVAC Systems, Bell/Fire Alarm Systems, Retrofit for Technology, Other to Room 100 (4852 NSF), Room 102 (750 NSF), Room 103 (130 NSF), Room 104 (608 NSF), Room 105 (1892 NSF), Room 105A (120 NSF), Room 105B (120 NSF), Room 105C (126 NSF), Room 105D (272 NSF), Room 106 (995 NSF), Room 106A (709 NSF), Room 107 (383 NSF), Room 107A (145 NSF), Room 108 (728 NSF), Room 112 (106 NSF), Room 114 (836 NSF), Room 114A (75 NSF), Room 115 (528 NSF), Room 115A (78 NSF), Room 115B (78 NSF), Room 115C (95 NSF), Room 116 (525 NSF), Room 116A (84 NSF), Room 117 (687 NSF), Room 117A (75 NSF), Room 118A (634 NSF), Room 118B (260 NSF), Room 118C (75 NSF), Room 119 (832 NSF), Room 119A (75 NSF), Room 120 (825 NSF), Room 120A (90 NSF), Room 121 (850 NSF), Room 121A (75 NSF), Room 123 (991 NSF), Room 123A (267 NSF), Room 123B (170 NSF), Room 124 (236 NSF), Room 124A (244 NSF), Room 125 (1020 NSF), Room 125A (183 NSF), Room 125B (174 NSF), Room 125C (174 NSF), Room 125D (158 NSF), Room 126 (1384 NSF), Room 126A (885 NSF), Room 126B (181 NSF), Room 127 (1008 NSF), Room 127D (158 NSF), Room 128 (1159 NSF), Room 190 (42 NSF), Room 191 (56 NSF), Room 193 (39 NSF), Room 195 (1190 NSF), Room 199 (608 NSF), Room 200 (3930 NSF), Room 200A (86 NSF), Room 203 (130 NSF), Room 204 (382 NSF), Room 204A (75 NSF), Room 205 (282 NSF), Room 205A (165 NSF), Room 205B (164 NSF), Room 205C (208 NSF), Room 206 (456 NSF), Room 206A (78 NSF), Room 207 (1023 NSF), Room 207A (268 NSF), Room 207B (71

6,315,736

EDUCATIONAL PLANT FIVE YEAR SURVEY REPORT

College:

3-COLLEGE OF CENTRAL FLORIDA

Survey:

Survey : 3 Version : 2

Status:

Active Pending

NSF), Room 207C (71 NSF), Room 207D (71 NSF), Room 207E (71 NSF), Room 207F (71 NSF), Room 207G (71 NSF), Room 207H (71 NSF), Room 207I (71 NSF), Room 207J (71 NSF), Room 207K (71 NSF), Room 207L (71 NSF), Room 207M (71 NSF), Room 208 (926 NSF), Room 208A (75 NSF), Room 210 (980 NSF), Room 210A (75 NSF), Room 212 (116 NSF), Room 214 (424 NSF), Room 214A (40 NSF), Room 215 (680 NSF), Room 215A (84 NSF), Room 216 (322 NSF), Room 217A (116 NSF), Room 217B (116 NSF), Room 217C (116 NSF), Room 217D (100 NSF), Room 217E (104 NSF), Room 217F (104 NSF), Room 217G (104 NSF), Room 217H (112 NSF), Room 218A (113 NSF), Room 218B (113 NSF), Room 218C (113 NSF), Room 218D (113 NSF), Room 218E (113 NSF), Room 218F (113 NSF), Room 219A (113 NSF), Room 219B (113 NSF), Room 219C (113 NSF), Room 219D (113 NSF), Room 219E (113 NSF), Room 219F (113 NSF), Room 220A (112 NSF), Room 220B (114 NSF), Room 220C (99 NSF), Room 220D (104 NSF), Room 220E (104 NSF), Room 220F (104 NSF), Room 220G (115 NSF), Room 220H (105 NSF), Room 220I (312 NSF), Room 224 (56 NSF)

Renovating Building Number - 2, Building Name - SCIENCE & TECHNOLOGY (425 SS), (44314 NSF) Apply Painting, Floor Cover, Electrical, Plumbing, Windows, Lighting, HVAC Systems, Bell/Fire Alarm Systems, Retrofit for Technology, Other to Room 100 (4852 NSF), Room 102 (750 NSF), Room 103 (130 NSF), Room 104 (608 NSF), Room 105 (1892 NSF), Room 105A (120 NSF), Room 105B (120 NSF), Room 105C (126 NSF), Room 105D (272 NSF), Room 106 (995 NSF), Room 106A (709 NSF), Room 107 (383 NSF), Room 107A (145 NSF), Room 108 (728 NSF), Room 112 (106 NSF), Room 114 (836 NSF), Room 114A (75 NSF), Room 115 (528 NSF), Room 115A (78 NSF), Room 115B (78 NSF), Room 115C (95 NSF), Room 116 (525 NSF), Room 116A (84 NSF), Room 117 (687 NSF), Room 117A (75 NSF), Room 118A (634 NSF), Room 118B (260 NSF), Room 118C (75 NSF), Room 119 (832 NSF), Room 119A (75 NSF), Room 120 (825 NSF), Room 120A (90 NSF), Room 121 (850 NSF), Room 121A (75 NSF), Room 123 (991 NSF), Room 123A (267 NSF), Room 123B (170 NSF), Room 124 (236 NSF), Room 124A (244 NSF), Room 125 (1020 NSF), Room 125A (183 NSF), Room 125B (174 NSF), Room 125C (174 NSF), Room 125D (158 NSF), Room 126 (1384 NSF), Room 126A (885 NSF), Room 126B (181 NSF), Room 127 (1008 NSF), Room 127D (158 NSF), Room 128 (1159 NSF), Room 190 (42 NSF), Room 191 (56 NSF), Room 193 (39 NSF), Room 195 (1190 NSF), Room 199 (608 NSF), Room 200 (3930 NSF), Room 200A (86 NSF), Room 203 (130 NSF), Room 204 (382 NSF), Room 204A (75 NSF), Room 205 (282 NSF), Room 205A (165 NSF), Room 205B (164 NSF), Room 205C (208 NSF), Room 206 (456 NSF), Room 206A (78 NSF), Room 207 (1023 NSF), Room 207A (268 NSF), Room 207B (71 NSF), Room 207C (71 NSF), Room 207D (71 NSF), Room 207E (71 NSF), Room 207F (71 NSF), Room 207G (71 NSF), Room 207H (71 NSF), Room 207I (71 NSF), Room 207J (71 NSF), Room 207K (71 NSF), Room 207L (71 NSF), Room 207M (71 NSF), Room 208 (926 NSF), Room 208A (75 NSF), Room 210 (980 NSF), Room 210A (75 NSF), Room 212 (116 NSF), Room 214 (424 NSF), Room 214A (40 NSF), Room 215 (680 NSF), Room 215A (84 NSF), Room 216 (322 NSF), Room 217A (116 NSF), Room 217B (116 NSF), Room 217C (116 NSF), Room 217D (100 NSF), Room 217E (104 NSF), Room 217F (104 NSF), Room 217G (104 NSF), Room 217H (112 NSF), Room 218A (113 NSF), Room 218B (113 NSF), Room 218C (113 NSF), Room 218D (113 NSF), Room 218E (113 NSF), Room 218F (113 NSF), Room 219A (113 NSF), Room 219B (113 NSF), Room 219C (113 NSF), Room 219D (113 NSF), Room 219E (113 NSF), Room 219F (113 NSF), Room 220A (112 NSF), Room 220B (114 NSF), Room 220C (99 NSF), Room 220D (104 NSF), Room 220E (104 NSF), Room 220F (104 NSF), Room 220G (115 NSF), Room 220H (105 NSF), Room 220I (312 NSF), Room 224 (56 NSF)

1.055

Renovating Building Number - 3, Building Name - LEARNING RESOURCES C (29 SS), (39334 NSF) Apply Painting, Floor Cover, Electrical, Plumbing, Windows, Lighting, Restrooms, HVAC Systems, Bell/Fire Alarm Systems, Retrofit for Technology, Other to Room 100 (2035 NSF), Room 103 (565 NSF), Room 106 (5946 NSF), Room 106A (230 NSF), Room 106B (161 NSF), Room 106C (868 NSF), Room 106D (44 NSF), Room 106E (18 NSF), Room 106F (36 NSF), Room 106H (58 NSF), Room 107 (188 NSF), Room 108 (64 NSF), Room 109 (202 NSF), Room 111 (101 NSF), Room 112 (743 NSF), Room 112A (110 NSF), Room 112B (260 NSF), Room 113 (760 NSF), Room 115 (477 NSF), Room 116 (106 NSF), Room 117 (444 NSF), Room 117A (206 NSF), Room 117B (145 NSF), Room 117C (175 NSF), Room 117D (547 NSF), Room 117E (66 NSF), Room 117F (97 NSF), Room 117G (110 NSF), Room 117H (154 NSF), Room 117J (154 NSF), Room 117K (148 NSF), Room 119 (196 NSF), Room 121 (193 NSF), Room 160 (107 NSF), Room 160A (48 NSF), Room 160B (52 NSF), Room 161 (136 NSF), Room 200 (165 NSF), Room 201 (12368 NSF), Room 201A (106 NSF), Room 201B (106 NSF), Room 201C (106 NSF), Room 201D (106 NSF), Room 201E (106 NSF), Room 201F (106 NSF), Room 201G (135 NSF), Room 201H (96 NSF), Room 201J (91 NSF), Room 201K (96 NSF), Room 202 (405 NSF), Room 203 (178 NSF), Room 204 (200 NSF), Room 205 (564 NSF), Room 207 (200 NSF), Room 208 (169 NSF), Room 209 (169 NSF), Room 210 (91 NSF), Room 211 (200 NSF), Room 212 (88 NSF), Room 213 (67 NSF), Room 214 (125 NSF), Room 215 (125 NSF), Room 216 (125 NSF), Room 217 (128 NSF), Room 218 (196 NSF), Room 219 (420 NSF), Room 219A (236 NSF), Room 101B (20 NSF), Room 101E (148 NSF), Room 101F (145 NSF), Room 101H (146 NSF), Room 101K (734 NSF), Room 101G (672 NSF), Room 101 (3584 NSF), Room 101J (662 NSF) Renovation Description: Renovating Building Number - 3, Building Name - LEARNING RESOURCES C (29 SS), (12874 NSF) Apply Painting, Floor Cover, Electrical, Plumbing, Windows, Lighting, HVAC Systems, Bell/Fire Alarm Systems, Retrofit for Technology, Other to Room 101 (3584 NSF), Room 101B (20 NSF), Room 101E (148 NSF), Room 101F (145

5,834,543

EDUCATIONAL PLANT FIVE YEAR SURVEY REPORT

College:

3-COLLEGE OF CENTRAL FLORIDA

Survey:

Survey : 3 Version : 2

Status:

Active Pending

NSF), Room 101G (672 NSF), Room 101H (146 NSF), Room 101J (662 NSF), Room 101K (734 NSF), Room 111 (101 NSF), Room 112 (743 NSF), Room 112A (110 NSF), Room 112B (260 NSF), Room 113 (400 NSF), Room 113A (92 NSF), Room 113B (195 NSF), Room 115 (477 NSF), Room 117 (444 NSF), Room 117A (206 NSF), Room 117B (145 NSF), Room 117C (175 NSF), Room 117D (547 NSF), Room 117F (97 NSF), Room 117G (110 NSF), Room 117H (154 NSF), Room 117J (154 NSF), Room 117K (148 NSF), Room 119 (196 NSF), Room 121 (193 NSF), Room 160 (107 NSF), Room 160A (48 NSF), Room 160B (52 NSF), Room 161 (136 NSF), Room 166 (608 NSF), Room 203 (178 NSF), Room 204 (200 NSF), Room 210 (91 NSF), Room 211 (200 NSF), Room 218 (196 NSF)

Renovating Building Number - 3, Building Name - LEARNING RESOURCES C (29 SS), (12874 NSF) Apply Painting, Floor Cover, Electrical, Plumbing, Windows, Lighting, HVAC Systems, Bell/Fire Alarm Systems, Retrofit for Technology, Other to Room 101 (3584 NSF), Room 101B (20 NSF), Room 101E (148 NSF), Room 101F (145 NSF), Room 101G (672 NSF), Room 101H (146 NSF), Room 101J (662 NSF), Room 101K (734 NSF), Room 111 (101 NSF), Room 112 (743 NSF), Room 112A (110 NSF), Room 112B (260 NSF), Room 113 (400 NSF), Room 113A (92 NSF), Room 113B (195 NSF), Room 115 (477 NSF), Room 117 (444 NSF), Room 117A (206 NSF), Room 117B (145 NSF), Room 117C (175 NSF), Room 117D (547 NSF), Room 117F (97 NSF), Room 117G (110 NSF), Room 117H (154 NSF), Room 117J (154 NSF), Room 117K (148 NSF), Room 119 (196 NSF), Room 121 (193 NSF), Room 160 (107 NSF), Room 160A (48 NSF), Room 160B (52 NSF), Room 161 (136 NSF), Room 166 (608 NSF), Room 203 (178 NSF), Room 204 (200 NSF), Room 210 (91 NSF), Room 211 (200 NSF), Room 218 (196 NSF)

1.056

Renovating Building Number - 4, Building Name - FINE ARTS/COMMUNICAT (175 SS), (41682 NSF) Apply Painting, Floor Cover, Electrical, Plumbing, Windows, Lighting, Restrooms, HVAC Systems, Bell/Fire Alarm Systems, Retrofit for Technology, Other to Room 100 (2307 NSF), Room 100B (78 NSF), Room 100C (100 NSF), Room 100D (37 NSF), Room 101A (130 NSF), Room 101B (256 NSF), Room 101C (105 NSF), Room 103 (135 NSF), Room 103A (126 NSF), Room 106 (192 NSF), Room 107 (168 NSF), Room 109 (163 NSF), Room 110 (73 NSF), Room 110A (936 NSF), Room 111 (169 NSF), Room 125 (2319 NSF), Room 125A (92 NSF), Room 126 (323 NSF), Room 127 (152 NSF), Room 128 (244 NSF), Room 129 (158 NSF), Room 130 (318 NSF), Room 130B (32 NSF), Room 131 (4128 NSF), Room 131A (100 NSF), Room 132 (195 NSF), Room 133 (2431 NSF), Room 134 (195 NSF), Room 135 (191 NSF), Room 135A (87 NSF), Room 135B (168 NSF), Room 137 (658 NSF), Room 138 (230 NSF), Room 138A (193 NSF), Room 138B (52 NSF), Room 138C (180 NSF), Room 139 (480 NSF), Room 139A (256 NSF), Room 140 (491 NSF), Room 140A (308 NSF), Room 141 (788 NSF), Room 141A (160 NSF), Room 210 (99 NSF), Room 211 (249 NSF), Room 212 (99 NSF), Room 214 (1056 NSF), Room 215 (310 NSF), Room 216 (212 NSF), Room 216A (81 NSF), Room 216B (47 NSF), Room 216C (72 NSF), Room 216D (572 NSF), Room 217 (217 NSF), Room 217A (81 NSF), Room 217B (47 NSF), Room 217C (73 NSF), Room 150 (3908 NSF), Room 151 (1832 NSF), Room 200 (1586 NSF), Room 200A (37 NSF), Room 200B (43 NSF), Room 201 (42 NSF), Room 202 (243 NSF), Room 202A (86 NSF), Room 202B (123 NSF), Room 202C (123 NSF), Room 202D (86 NSF), Room 202E (89 NSF), Room 203 (40 NSF), Room 113 (222 NSF), Room 208 (160 NSF), Room 207 (683 NSF), Room 207A (75 NSF), Room 104 (535 NSF), Room 104A (85 NSF), Room 206B (159 NSF), Room 204 (1161 NSF), Room 204A (100 NSF), Room 204B (200 NSF), Room 205 (746 NSF), Room 205A (75 NSF), Room 206 (810 NSF), Room 208C (100 NSF), Room 114 (75 NSF), Room 116 (71 NSF), Room 117 (71 NSF), Room 118 (77 NSF), Room 119 (77 NSF), Room 120 (111 NSF), Room 121 (58 NSF), Room 122 (1556 NSF), Room 122A (80 NSF), Room 122B (80 NSF), Room 122C (61 NSF), Room 122D (30 NSF), Room 123 (1131 NSF), Room 112 (75 NSF), Room 105 (257 NSF), Room 142 (1404 NSF) Renovation Description: Renovating Building Number - 4, Building Name - FINE ARTS/COMMUNICAT (175 SS), (45969 NSF) Apply Painting, Floor Cover, Electrical, Plumbing, Windows, Lighting, HVAC Systems, Bell/Fire Alarm Systems, Retrofit for Technology, Other to Room 100 (2307 NSF), Room 100A (54 NSF), Room 100B (78 NSF), Room 100C (100 NSF), Room 100D (37 NSF), Room 100E (43 NSF), Room 101A (130 NSF), Room 101B (256 NSF), Room 101C (105 NSF), Room 103 (135 NSF), Room 103A (126 NSF), Room 104 (535 NSF), Room 104A (85 NSF), Room 105 (257 NSF), Room 106 (192 NSF), Room 107 (168 NSF), Room 108 (162 NSF), Room 109 (163 NSF), Room 110 (73 NSF), Room 110A (936 NSF), Room 111 (169 NSF), Room 112 (75 NSF), Room 113 (222 NSF), Room 114 (75 NSF), Room 116 (71 NSF), Room 117 (71 NSF), Room 118 (77 NSF), Room 119 (77 NSF), Room 120 (111 NSF), Room 121 (58 NSF), Room 122 (1556 NSF), Room 122A (80 NSF), Room 122B (80 NSF), Room 122C (61 NSF), Room 122D (30 NSF), Room 123 (1131 NSF), Room 123A (30 NSF), Room 123B (30 NSF), Room 124 (2896 NSF), Room 125 (2319 NSF), Room 125A (92 NSF), Room 126 (323 NSF), Room 127 (152 NSF), Room 128 (244 NSF), Room 129 (158 NSF), Room 130 (318 NSF), Room 130B (32 NSF), Room 131 (4128 NSF), Room 131A (100 NSF), Room 132 (195 NSF), Room 133 (2431 NSF), Room 134 (195 NSF), Room 135 (191 NSF), Room 135A (87 NSF), Room 135B (168 NSF), Room 136 (90 NSF), Room 137 (658 NSF), Room 138 (230 NSF), Room 138A (193 NSF), Room 138B (52 NSF), Room 138C (180 NSF), Room 139 (480 NSF), Room 139A (256 NSF), Room 140 (491 NSF), Room 140A (308 NSF), Room 141 (788 NSF), Room 141A (160 NSF), Room 142 (1404 NSF), Room 150 (3908 NSF), Room 151 (1832 NSF), Room 200 (1586 NSF), Room 200A (37 NSF), Room 200B (43 NSF), Room 201 (42 NSF), Room 202 (243 NSF), Room 202A (86 NSF), Room 202B (123 NSF), Room 202C (123 NSF), Room 202D (86 NSF), Room 202E (89 NSF), Room 203 (40 NSF), Room

6,182,829

EDUCATIONAL PLANT FIVE YEAR SURVEY REPORT

College:

3-COLLEGE OF CENTRAL FLORIDA

Survey:

Survey : 3 Version : 2

Status:

Active Pending

204 (1161 NSF), Room 204A (100 NSF), Room 204B (200 NSF), Room 205 (746 NSF), Room 205A (75 NSF), Room 206 (810 NSF), Room 206A (132 NSF), Room 206B (159 NSF), Room 207 (683 NSF), Room 207A (75 NSF), Room 208 (160 NSF), Room 208C (100 NSF), Room 209 (425 NSF), Room 210 (99 NSF), Room 211 (249 NSF), Room 212 (99 NSF), Room 213 (425 NSF), Room 214 (1056 NSF), Room 215 (310 NSF), Room 216 (212 NSF), Room 216A (81 NSF), Room 216B (47 NSF), Room 216C (72 NSF), Room 216D (572 NSF), Room 217 (217 NSF), Room 217A (81 NSF), Room 217B (47 NSF), Room 217C (73 NSF)

Renovating Building Number - 4, Building Name - FINE ARTS/COMMUNICAT (175 SS), (45969 NSF) Apply Painting, Floor Cover, Electrical, Plumbing, Windows, Lighting, HVAC Systems, Bell/Fire Alarm Systems, Retrofit for Technology, Other to Room 100 (2307 NSF), Room 100A (54 NSF), Room 100B (78 NSF), Room 100C (100 NSF), Room 100D (37 NSF), Room 100E (43 NSF), Room 101A (130 NSF), Room 101B (256 NSF), Room 101C (105 NSF), Room 103 (135 NSF), Room 103A (126 NSF), Room 104 (535 NSF), Room 104A (85 NSF), Room 105 (257 NSF), Room 106 (192 NSF), Room 107 (168 NSF), Room 108 (162 NSF), Room 109 (163 NSF), Room 110 (73 NSF), Room 110A (936 NSF), Room 111 (169 NSF), Room 112 (75 NSF), Room 113 (222 NSF), Room 114 (75 NSF), Room 116 (71 NSF), Room 117 (71 NSF), Room 118 (77 NSF), Room 119 (77 NSF), Room 120 (111 NSF), Room 121 (58 NSF), Room 122 (1556 NSF), Room 122A (80 NSF), Room 122B (80 NSF), Room 122C (61 NSF), Room 122D (30 NSF), Room 123 (1131 NSF), Room 123A (30 NSF), Room 123B (30 NSF), Room 124 (2896 NSF), Room 125 (2319 NSF), Room 125A (92 NSF), Room 126 (323 NSF), Room 127 (152 NSF), Room 128 (244 NSF), Room 129 (158 NSF), Room 130 (318 NSF), Room 130B (32 NSF), Room 131 (4128 NSF), Room 131A (100 NSF), Room 132 (195 NSF), Room 133 (2431 NSF), Room 134 (195 NSF), Room 135 (191 NSF), Room 135A (87 NSF), Room 135B (168 NSF), Room 136 (90 NSF), Room 137 (658 NSF), Room 138 (230 NSF), Room 138A (193 NSF), Room 138B (52 NSF), Room 138C (180 NSF), Room 139 (480 NSF), Room 139A (256 NSF), Room 140 (491 NSF), Room 140A (308 NSF), Room 141 (788 NSF), Room 141A (160 NSF), Room 142 (1404 NSF), Room 150 (3908 NSF), Room 151 (1832 NSF), Room 200 (1586 NSF), Room 200A (37 NSF), Room 200B (43 NSF), Room 201 (42 NSF), Room 202 (243 NSF), Room 202A (86 NSF), Room 202B (123 NSF), Room 202C (123 NSF), Room 202D (86 NSF), Room 202E (89 NSF), Room 203 (40 NSF), Room 204 (1161 NSF), Room 204A (100 NSF), Room 204B (200 NSF), Room 205 (746 NSF), Room 205A (75 NSF), Room 206 (810 NSF), Room 206A (132 NSF), Room 206B (159 NSF), Room 207 (683 NSF), Room 207A (75 NSF), Room 208 (160 NSF), Room 208C (100 NSF), Room 209 (425 NSF), Room 210 (99 NSF), Room 211 (249 NSF), Room 212 (99 NSF), Room 213 (425 NSF), Room 214 (1056 NSF), Room 215 (310 NSF), Room 216 (212 NSF), Room 216A (81 NSF), Room 216B (47 NSF), Room 216C (72 NSF), Room 216D (572 NSF), Room 217 (217 NSF), Room 217A (81 NSF), Room 217B (47 NSF), Room 217C (73 NSF)

1.057 Renovating Building Number - 10, Building Name - PLANT OPERATIONS (0 SS), (5120 NSF) 759,466

Apply Painting, Floor Cover, Electrical, Plumbing, Windows, Lighting, Restrooms, HVAC Systems, Bell/Fire Alarm Systems, Retrofit for Technology, Other to Room 100 (128 NSF), Room 101 (302 NSF), Room 101A (73 NSF), Room 101B (125 NSF), Room 102 (207 NSF), Room 103 (86 NSF), Room 103A (436 NSF), Room 104 (161 NSF), Room 105 (178 NSF), Room 106 (527 NSF), Room 106A (252 NSF), Room 107 (185 NSF), Room 108 (192 NSF), Room 109 (223 NSF), Room 110 (370 NSF), Room 111 (193 NSF), Room 111A (225 NSF), Room 114 (414 NSF), Room 115 (600 NSF), Room 117 (231 NSF), Room 117C (8 NSF), Room 117D (4 NSF) Renovation Description: Renovating Building Number - 10, Building Name - PLANT OPERATIONS (0 SS), (5743 NSF) Apply Painting, Floor Cover, Electrical, Plumbing, Windows, Lighting, HVAC Systems, Bell/Fire Alarm Systems, Retrofit for Technology, Other to Room 100 (128 NSF), Room 101 (302 NSF), Room 101A (73 NSF), Room 101B (125 NSF), Room 102 (207 NSF), Room 103 (86 NSF), Room 103A (436 NSF), Room 104 (161 NSF), Room 105 (178 NSF), Room 106 (527 NSF), Room 106A (252 NSF), Room 107 (185 NSF), Room 108 (192 NSF), Room 109 (223 NSF), Room 110 (370 NSF), Room 111 (193 NSF), Room 111A (225 NSF), Room 114 (414 NSF), Room 115 (600 NSF), Room 116 (68 NSF), Room 117 (231 NSF), Room 117A (118 NSF), Room 117B (54 NSF), Room 117C (8 NSF), Room 117D (4 NSF), Room 118 (275 NSF), Room 119 (108 NSF)

Renovating Building Number - 10, Building Name - PLANT OPERATIONS (0 SS), (5743 NSF) Apply Painting, Floor Cover, Electrical, Plumbing, Windows, Lighting, HVAC Systems, Bell/Fire Alarm Systems, Retrofit for Technology, Other to Room 100 (128 NSF), Room 101 (302 NSF), Room 101A (73 NSF), Room 101B (125 NSF), Room 102 (207 NSF), Room 103 (86 NSF), Room 103A (436 NSF), Room 104 (161 NSF), Room 105 (178 NSF), Room 106 (527 NSF), Room 106A (252 NSF), Room 107 (185 NSF), Room 108 (192 NSF), Room 109 (223 NSF), Room 110 (370 NSF), Room 111 (193 NSF), Room 111A (225 NSF), Room 114 (414 NSF), Room 115 (600 NSF), Room 116 (68 NSF), Room 117 (231 NSF), Room 117A (118 NSF), Room 117B (54 NSF), Room 117C (8 NSF), Room 117D (4 NSF), Room 118 (275 NSF), Room 119 (108 NSF)

1.058 Renovating Building Number - 9, Building Name - INSTRUCTIONAL CENTER (118 SS), (9836 NSF) 1,459,006

Apply Painting, Floor Cover, Electrical, Plumbing, Windows, Lighting, Restrooms, HVAC Systems, Bell/Fire Alarm Systems, Retrofit for Technology, Other to Room 100 (1429 NSF), Room 151 (271 NSF), Room 101 (902 NSF), Room 101A (96 NSF), Room 101B (154 NSF), Room 101C (26 NSF), Room 101D (119 NSF), Room 102 (192 NSF), Room 102A (140 NSF), Room 102B (180 NSF), Room 104 (244 NSF), Room 105 (106 NSF), Room 107A (110 NSF), Room 111 (114 NSF), Room 112 (111 NSF), Room 113 (111 NSF), Room 114

EDUCATIONAL PLANT FIVE YEAR SURVEY REPORT

College:

Survey:

Status:

3-COLLEGE OF CENTRAL FLORIDA

Survey : 3 Version : 2

Active Pending

(111 NSF), Room 108 (684 NSF), Room 108A (75 NSF), Room 110 (760 NSF), Room 110A (88 NSF), Room 103 (533 NSF), Room 103A (75 NSF), Room 100E (264 NSF), Room 107D (83 NSF), Room 107B (175 NSF), Room 107 (1184 NSF), Room 106 (1381 NSF), Room 107C (118 NSF) Renovation Description: Renovating Building Number - 9, Building Name - INSTRUCTIONAL CENTER (124 SS), (11731 NSF) Apply Painting, Floor Cover, Electrical, Plumbing, Windows, Lighting, HVAC Systems, Bell/Fire Alarm Systems, Retrofit for Technology, Other to Room 100 (1429 NSF), Room 100A (97 NSF), Room 100B (53 NSF), Room 100C (200 NSF), Room 100D (237 NSF), Room 100E (264 NSF), Room 102 (192 NSF), Room 102A (140 NSF), Room 102B (180 NSF), Room 103 (533 NSF), Room 103A (75 NSF), Room 104 (244 NSF), Room 105 (106 NSF), Room 106 (596 NSF), Room 107 (1184 NSF), Room 107A (110 NSF), Room 107B (175 NSF), Room 107C (118 NSF), Room 107D (83 NSF), Room 108 (684 NSF), Room 108A (75 NSF), Room 109 (785 NSF), Room 109A (75 NSF), Room 110 (760 NSF), Room 110A (88 NSF), Room 111 (114 NSF), Room 112 (111 NSF), Room 113 (111 NSF), Room 114 (111 NSF), Room 150 (124 NSF), Room 150A (826 NSF), Room 151 (271 NSF), Room 151A (504 NSF), Room 152 (42 NSF), Room 153 (1034 NSF)

Renovating Building Number - 9, Building Name - INSTRUCTIONAL CENTER (124 SS), (11731 NSF) Apply Painting, Floor Cover, Electrical, Plumbing, Windows, Lighting, HVAC Systems, Bell/Fire Alarm Systems, Retrofit for Technology, Other to Room 100 (1429 NSF), Room 100A (97 NSF), Room 100B (53 NSF), Room 100C (200 NSF), Room 100D (237 NSF), Room 100E (264 NSF), Room 102 (192 NSF), Room 102A (140 NSF), Room 102B (180 NSF), Room 103 (533 NSF), Room 103A (75 NSF), Room 104 (244 NSF), Room 105 (106 NSF), Room 106 (596 NSF), Room 107 (1184 NSF), Room 107A (110 NSF), Room 107B (175 NSF), Room 107C (118 NSF), Room 107D (83 NSF), Room 108 (684 NSF), Room 108A (75 NSF), Room 109 (785 NSF), Room 109A (75 NSF), Room 110 (760 NSF), Room 110A (88 NSF), Room 111 (114 NSF), Room 112 (111 NSF), Room 113 (111 NSF), Room 114 (111 NSF), Room 150 (124 NSF), Room 150A (826 NSF), Room 151 (271 NSF), Room 151A (504 NSF), Room 152 (42 NSF), Room 153 (1034 NSF)

1.059 Renovating Building Number - 11, Building Name - BUS. SUPPORT/VETERAN (0 SS), (3294 NSF) 488,609
 Apply Painting, Floor Cover, Electrical, Plumbing, Windows, Lighting, Restrooms, HVAC Systems, Bell/Fire Alarm Systems, Retrofit for Technology, Other to Room 100 (816 NSF), Room 100A (18 NSF), Room 101 (316 NSF), Room 101A (118 NSF), Room 101B (103 NSF), Room 101C (103 NSF), Room 101D (61 NSF), Room 102 (724 NSF), Room 106 (128 NSF), Room 107 (179 NSF), Room 108 (385 NSF), Room 108A (77 NSF), Room 109 (120 NSF), Room 151 (146 NSF) Renovation Description: Renovating Building Number - 11, Building Name - BUS. SUPPORT/VETERAN (0 SS), (3501 NSF) Apply Painting, Floor Cover, Electrical, Plumbing, Windows, Lighting, HVAC Systems, Bell/Fire Alarm Systems, Retrofit for Technology, Other to Room 100 (816 NSF), Room 100A (18 NSF), Room 101 (316 NSF), Room 101A (118 NSF), Room 101B (103 NSF), Room 101C (103 NSF), Room 101D (61 NSF), Room 102 (724 NSF), Room 103 (51 NSF), Room 104 (53 NSF), Room 106 (128 NSF), Room 107 (179 NSF), Room 108 (385 NSF), Room 108A (77 NSF), Room 109 (120 NSF), Room 150 (103 NSF), Room 151 (146 NSF)

Renovating Building Number - 11, Building Name - BUS. SUPPORT/VETERAN (0 SS), (3501 NSF) Apply Painting, Floor Cover, Electrical, Plumbing, Windows, Lighting, HVAC Systems, Bell/Fire Alarm Systems, Retrofit for Technology, Other to Room 100 (816 NSF), Room 100A (18 NSF), Room 101 (316 NSF), Room 101A (118 NSF), Room 101B (103 NSF), Room 101C (103 NSF), Room 101D (61 NSF), Room 102 (724 NSF), Room 103 (51 NSF), Room 104 (53 NSF), Room 106 (128 NSF), Room 107 (179 NSF), Room 108 (385 NSF), Room 108A (77 NSF), Room 109 (120 NSF), Room 150 (103 NSF), Room 151 (146 NSF)

1.060 Renovating Building Number - 12, Building Name - AQUATIC CENTER (0 SS), (3383 NSF) 501,811
 Apply Painting, Floor Cover, Electrical, Plumbing, Windows, Lighting, Restrooms, HVAC Systems, Bell/Fire Alarm Systems, Retrofit for Technology, Other to Room 100 (622 NSF), Room 100B (272 NSF), Room 100C (134 NSF), Room 101 (163 NSF), Room 102 (103 NSF), Room 103 (1044 NSF), Room 104 (1045 NSF) Renovation Description: Renovating Building Number - 12, Building Name - AQUATIC CENTER (0 SS), (4100 NSF) Apply Painting, Floor Cover, Electrical, Plumbing, Windows, Lighting, HVAC Systems, Bell/Fire Alarm Systems, Retrofit for Technology, Other to Room 100 (622 NSF), Room 100A (43 NSF), Room 100B (272 NSF), Room 100C (134 NSF), Room 100D (28 NSF), Room 101 (163 NSF), Room 101A (27 NSF), Room 102 (103 NSF), Room 103 (1044 NSF), Room 104 (1045 NSF), Room 150 (595 NSF), Room 150A (24 NSF)

Renovating Building Number - 12, Building Name - AQUATIC CENTER (0 SS), (4100 NSF) Apply Painting, Floor Cover, Electrical, Plumbing, Windows, Lighting, HVAC Systems, Bell/Fire Alarm Systems, Retrofit for Technology, Other to Room 100 (622 NSF), Room 100A (43 NSF), Room 100B (272 NSF), Room 100C (134 NSF), Room 100D (28 NSF), Room 101 (163 NSF), Room 101A (27 NSF), Room 102 (103 NSF), Room 103 (1044 NSF), Room 104 (1045 NSF), Room 150 (595 NSF), Room 150A (24 NSF)

1.061 Renovating Building Number - 16, Building Name - PERSONAL SERV. INST. (15 SS), (8475 NSF) 1,257,125
 Apply Painting, Floor Cover, Electrical, Plumbing, Windows, Lighting, Restrooms, HVAC Systems, Bell/Fire Alarm Systems, Retrofit for Technology, Other to Room 100 (2730 NSF), Room 101 (200 NSF), Room 102 (108 NSF), Room 103 (108 NSF), Room 104 (108 NSF), Room 105 (108 NSF), Room 116 (121 NSF), Room 117 (126 NSF), Room 118 (140 NSF), Room 119 (140 NSF), Room 120 (143 NSF), Room 121 (169 NSF), Room 122 (285 NSF), Room 123 (174 NSF), Room 124A (615 NSF), Room 150 (44 NSF), Room 151 (44 NSF), Room 152

EDUCATIONAL PLANT FIVE YEAR SURVEY REPORT

College:

Survey:

Status:

3-COLLEGE OF CENTRAL FLORIDA

Survey : 3 Version : 2

Active Pending

(44 NSF), Room 124 (102 NSF), Room 106 (149 NSF), Room 107 (149 NSF), Room 108 (149 NSF), Room 109 (212 NSF), Room 110 (1170 NSF), Room 110A (300 NSF), Room 111 (149 NSF), Room 112 (149 NSF), Room 113 (149 NSF), Room 114 (330 NSF), Room 115 (60 NSF) Renovation Description: Renovating Building Number - 16, Building Name - PERSONAL SERV. INST. (15 SS), (10091 NSF) Apply Floor Cover, Electrical, Plumbing, Windows, Lighting, HVAC Systems, Bell/Fire Alarm Systems, Retrofit for Technology, Other, Painting to Room 100 (2730 NSF), Room 100A (140 NSF), Room 100B (173 NSF), Room 101 (200 NSF), Room 102 (108 NSF), Room 103 (108 NSF), Room 104 (108 NSF), Room 105 (108 NSF), Room 106 (149 NSF), Room 107 (149 NSF), Room 108 (149 NSF), Room 109 (212 NSF), Room 110 (1170 NSF), Room 110A (300 NSF), Room 111 (149 NSF), Room 112 (149 NSF), Room 113 (149 NSF), Room 114 (330 NSF), Room 115 (60 NSF), Room 116 (121 NSF), Room 117 (126 NSF), Room 118 (140 NSF), Room 119 (140 NSF), Room 120 (143 NSF), Room 121 (169 NSF), Room 122 (285 NSF), Room 123 (174 NSF), Room 124 (102 NSF), Room 124A (615 NSF), Room 150 (44 NSF), Room 151 (44 NSF), Room 152 (44 NSF), Room 155 (1303 NSF)

Renovating Building Number - 16, Building Name - PERSONAL SERV. INST. (15 SS), (10091 NSF) Apply Floor Cover, Electrical, Plumbing, Windows, Lighting, HVAC Systems, Bell/Fire Alarm Systems, Retrofit for Technology, Other, Painting to Room 100 (2730 NSF), Room 100A (140 NSF), Room 100B (173 NSF), Room 101 (200 NSF), Room 102 (108 NSF), Room 103 (108 NSF), Room 104 (108 NSF), Room 105 (108 NSF), Room 106 (149 NSF), Room 107 (149 NSF), Room 108 (149 NSF), Room 109 (212 NSF), Room 110 (1170 NSF), Room 110A (300 NSF), Room 111 (149 NSF), Room 112 (149 NSF), Room 113 (149 NSF), Room 114 (330 NSF), Room 115 (60 NSF), Room 116 (121 NSF), Room 117 (126 NSF), Room 118 (140 NSF), Room 119 (140 NSF), Room 120 (143 NSF), Room 121 (169 NSF), Room 122 (285 NSF), Room 123 (174 NSF), Room 124 (102 NSF), Room 124A (615 NSF), Room 150 (44 NSF), Room 151 (44 NSF), Room 152 (44 NSF), Room 155 (1303 NSF)

1.062 Renovating Building Number - 18, Building Name - LEARNING LAB SCH/CHI (0 SS), (5014 NSF) Apply Painting, Floor Cover, Electrical, Plumbing, Windows, Lighting, Restrooms, HVAC Systems, Bell/Fire Alarm Systems, Retrofit for Technology, Other to Room 100 (1168 NSF), Room 100A (74 NSF), Room 101 (340 NSF), Room 102 (81 NSF), Room 105 (616 NSF), Room 105A (172 NSF), Room 106 (34 NSF), Room 107 (72 NSF), Room 108 (43 NSF), Room 111 (50 NSF), Room 112 (128 NSF), Room 113 (37 NSF), Room 120 (40 NSF), Room 121 (117 NSF), Room 122 (59 NSF), Room 123 (68 NSF), Room 124 (69 NSF), Room 127 (26 NSF), Room 128 (523 NSF), Room 129 (977 NSF), Room 115 (320 NSF) Renovation Description: Renovating Building Number - 18, Building Name - LEARNING LAB SCH/CHI (0 SS), (5703 NSF) Apply Painting, Floor Cover, Electrical, Plumbing, Windows, Lighting, HVAC Systems, Bell/Fire Alarm Systems, Retrofit for Technology, Other to Room 100 (1168 NSF), Room 100A (74 NSF), Room 101 (340 NSF), Room 102 (81 NSF), Room 103 (28 NSF), Room 104 (28 NSF), Room 105 (616 NSF), Room 105A (172 NSF), Room 106 (34 NSF), Room 107 (72 NSF), Room 108 (43 NSF), Room 109 (43 NSF), Room 110 (48 NSF), Room 111 (50 NSF), Room 112 (128 NSF), Room 113 (37 NSF), Room 115 (320 NSF), Room 116 (50 NSF), Room 117 (84 NSF), Room 118 (216 NSF), Room 119 (140 NSF), Room 120 (40 NSF), Room 121 (117 NSF), Room 122 (59 NSF), Room 123 (68 NSF), Room 124 (69 NSF), Room 125 (26 NSF), Room 126 (26 NSF), Room 127 (26 NSF), Room 128 (523 NSF), Room 129 (977 NSF)

Renovating Building Number - 18, Building Name - LEARNING LAB SCH/CHI (0 SS), (5703 NSF) Apply Painting, Floor Cover, Electrical, Plumbing, Windows, Lighting, HVAC Systems, Bell/Fire Alarm Systems, Retrofit for Technology, Other to Room 100 (1168 NSF), Room 100A (74 NSF), Room 101 (340 NSF), Room 102 (81 NSF), Room 103 (28 NSF), Room 104 (28 NSF), Room 105 (616 NSF), Room 105A (172 NSF), Room 106 (34 NSF), Room 107 (72 NSF), Room 108 (43 NSF), Room 109 (43 NSF), Room 110 (48 NSF), Room 111 (50 NSF), Room 112 (128 NSF), Room 113 (37 NSF), Room 115 (320 NSF), Room 116 (50 NSF), Room 117 (84 NSF), Room 118 (216 NSF), Room 119 (140 NSF), Room 120 (40 NSF), Room 121 (117 NSF), Room 122 (59 NSF), Room 123 (68 NSF), Room 124 (69 NSF), Room 125 (26 NSF), Room 126 (26 NSF), Room 127 (26 NSF), Room 128 (523 NSF), Room 129 (977 NSF)

1.063 Renovating Building Number - 51, Building Name - E. CAMPUS CHILLER PL (0 SS), (2933 NSF) Apply Painting, Floor Cover, Electrical, Plumbing, Windows, Lighting, Restrooms, HVAC Systems, Bell/Fire Alarm Systems, Retrofit for Technology to Room 101 (2615 NSF), Room 101A (242 NSF), Room 102 (76 NSF) Renovation Description: Renovating Building Number - 51, Building Name - E. CAMPUS CHILLER PL (0 SS), (5063 NSF) Apply Painting, Floor Cover, Electrical, Plumbing, Windows, Lighting, HVAC Systems, Bell/Fire Alarm Systems, Retrofit for Technology, Other to Room 101 (2615 NSF), Room 101A (242 NSF), Room 102 (76 NSF), Room 103 (2130 NSF)

Renovating Building Number - 51, Building Name - E. CAMPUS CHILLER PL (0 SS), (5063 NSF) Apply Painting, Floor Cover, Electrical, Plumbing, Windows, Lighting, HVAC Systems, Bell/Fire Alarm Systems, Retrofit for Technology, Other to Room 101 (2615 NSF), Room 101A (242 NSF), Room 102 (76 NSF), Room 103 (2130 NSF)

1.064 Renovating Building Number - 54, Building Name - ADT WEIGHT ROOM (0 SS), (1163 NSF) Apply Painting, Floor Cover, Electrical, Plumbing, Windows, Lighting, Restrooms, HVAC Systems, Bell/Fire Alarm Systems, Retrofit for Technology to Room 101 (1163 NSF) Renovation Description: Renovating Building Number - 54, Building Name - ADT WEIGHT ROOM (0 SS), (2023

EDUCATIONAL PLANT FIVE YEAR SURVEY REPORT

College:

Survey:

Status:

3-COLLEGE OF CENTRAL FLORIDA

Survey : 3 Version : 2

Active Pending

NSF) Apply Painting, Floor Cover, Electrical, Plumbing, Windows, Lighting, HVAC Systems, Bell/Fire Alarm Systems, Retrofit for Technology, Other to Room 101 (1163 NSF), Room 102 (60 NSF), Room 107 (800 NSF)		
Renovating Building Number - 54, Building Name - ADT WEIGHT ROOM (0 SS), (2023 NSF) Apply Painting, Floor Cover, Electrical, Plumbing, Windows, Lighting, HVAC Systems, Bell/Fire Alarm Systems, Retrofit for Technology, Other to Room 101 (1163 NSF), Room 102 (60 NSF), Room 107 (800 NSF)		
1.065 Renovating Building Number - 55, Building Name - PUBLIC SAFETY (0 SS), (1206 NSF) Apply Painting, Floor Cover, Electrical, Plumbing, Windows, Lighting, Restrooms, HVAC Systems, Bell/Fire Alarm Systems, Retrofit for Technology, Other to Room 100 (538 NSF), Room 101 (173 NSF), Room 102 (333 NSF), Room 105 (117 NSF), Room 145 (45 NSF) Renovation Description: Renovating Building Number - 55, Building Name - PUBLIC SAFETY (0 SS), (1558 NSF) Apply Painting, Floor Cover, Electrical, Plumbing, Windows, Lighting, HVAC Systems, Bell/Fire Alarm Systems, Retrofit for Technology, Other to Room 100 (538 NSF), Room 101 (173 NSF), Room 102 (333 NSF), Room 103 (30 NSF), Room 104 (42 NSF), Room 105 (117 NSF), Room 106 (280 NSF), Room 145 (45 NSF)	178,890	
Renovating Building Number - 55, Building Name - PUBLIC SAFETY (0 SS), (1558 NSF) Apply Painting, Floor Cover, Electrical, Plumbing, Windows, Lighting, HVAC Systems, Bell/Fire Alarm Systems, Retrofit for Technology, Other to Room 100 (538 NSF), Room 101 (173 NSF), Room 102 (333 NSF), Room 103 (30 NSF), Room 104 (42 NSF), Room 105 (117 NSF), Room 106 (280 NSF), Room 145 (45 NSF)		
1.066 Renovating Building Number - 56, Building Name - COMMUNICATION SYSTEM (0 SS), (318 NSF) Apply Painting, Floor Cover, Electrical, Plumbing, Windows, Lighting, Restrooms, HVAC Systems, Bell/Fire Alarm Systems, Retrofit for Technology, Other to Room 102 (238 NSF), Room 102A (80 NSF) Renovation Description: Renovating Building Number - 56, Building Name - COMMUNICATION SYSTEM (0 SS), (624 NSF) Apply Painting, Floor Cover, Electrical, Plumbing, Windows, Lighting, HVAC Systems, Bell/Fire Alarm Systems, Retrofit for Technology, Other to Room 101 (306 NSF), Room 102 (238 NSF), Room 102A (80 NSF)	47,169	
Renovating Building Number - 56, Building Name - COMMUNICATION SYSTEM (0 SS), (624 NSF) Apply Painting, Floor Cover, Electrical, Plumbing, Windows, Lighting, HVAC Systems, Bell/Fire Alarm Systems, Retrofit for Technology, Other to Room 101 (306 NSF), Room 102 (238 NSF), Room 102A (80 NSF)		
1.067 Renovating Building Number - 57, Building Name - CENTRAL RECEIVING (0 SS), (12250 NSF) Apply Painting, Floor Cover, Electrical, Plumbing, Windows, Lighting, Restrooms, HVAC Systems, Bell/Fire Alarm Systems, Retrofit for Technology, Other to Room 101 (306 NSF), Room 101A (974 NSF), Room 102 (581 NSF), Room 102A (160 NSF), Room 103 (4900 NSF), Room 104 (2690 NSF), Room 105 (207 NSF), Room 201 (2432 NSF) Renovation Description: Renovating Building Number - 57, Building Name - CENTRAL RECEIVING (0 SS), (12250 NSF) Apply Painting, Floor Cover, Electrical, Plumbing, Windows, Lighting, HVAC Systems, Bell/Fire Alarm Systems, Retrofit for Technology, Other to Room 101 (306 NSF), Room 101A (974 NSF), Room 102 (581 NSF), Room 102A (160 NSF), Room 103 (4900 NSF), Room 104 (2690 NSF), Room 105 (207 NSF), Room 201 (2432 NSF)	1,817,083	
Renovating Building Number - 57, Building Name - CENTRAL RECEIVING (0 SS), (12250 NSF) Apply Painting, Floor Cover, Electrical, Plumbing, Windows, Lighting, HVAC Systems, Bell/Fire Alarm Systems, Retrofit for Technology, Other to Room 101 (306 NSF), Room 101A (974 NSF), Room 102 (581 NSF), Room 102A (160 NSF), Room 103 (4900 NSF), Room 104 (2690 NSF), Room 105 (207 NSF), Room 201 (2432 NSF)		
1.068 Renovating Building Number - 58, Building Name - ELECTRICAL/PAINT SHO (0 SS), (2290 NSF) Apply Painting, Floor Cover, Electrical, Plumbing, Windows, Lighting, Restrooms, HVAC Systems, Bell/Fire Alarm Systems, Retrofit for Technology, Other to Room 101 (1600 NSF), Room 102 (690 NSF) Renovation Description: Renovating Building Number - 58, Building Name - ELECTRICAL/PAINT SHO (0 SS), (2808 NSF) Apply Painting, Floor Cover, Electrical, Plumbing, Windows, Lighting, HVAC Systems, Bell/Fire Alarm Systems, Retrofit for Technology, Other to Room 100 (518 NSF), Room 101 (1600 NSF), Room 102 (690 NSF)	339,683	
Renovating Building Number - 58, Building Name - ELECTRICAL/PAINT SHO (0 SS), (2808 NSF) Apply Painting, Floor Cover, Electrical, Plumbing, Windows, Lighting, HVAC Systems, Bell/Fire Alarm Systems, Retrofit for Technology, Other to Room 100 (518 NSF), Room 101 (1600 NSF), Room 102 (690 NSF)		
1.069 Renovating Building Number - 59, Building Name - WAREHOUSE (0 SS), (1056 NSF) Apply Painting, Floor Cover, Electrical, Plumbing, Windows, Lighting, Restrooms, HVAC Systems, Bell/Fire Alarm Systems, Retrofit for Technology, Other to Room 101 (443 NSF), Room 101A (100 NSF), Room 102 (206 NSF), Room 103 (307 NSF) Renovation Description: Renovating Building Number - 59, Building Name - WAREHOUSE (0 SS), (1930 NSF) Apply Painting, Floor Cover, Electrical, Plumbing, Windows, Lighting, HVAC Systems, Bell/Fire Alarm Systems, Retrofit for Technology, Other to Room 100 (874 NSF), Room 101 (443 NSF), Room 101A (100 NSF), Room 102 (206 NSF), Room 103 (307 NSF)	156,640	
Renovating Building Number - 59, Building Name - WAREHOUSE (0 SS), (1930 NSF) Apply		

EDUCATIONAL PLANT FIVE YEAR SURVEY REPORT

College:

Survey:

Status:

3-COLLEGE OF CENTRAL FLORIDA

Survey : 3 Version : 2

Active Pending

1.070	<p>Painting, Floor Cover, Electrical, Plumbing, Windows, Lighting, HVAC Systems, Bell/Fire Alarm Systems, Retrofit for Technology, Other to Room 100 (874 NSF), Room 101 (443 NSF), Room 101A (100 NSF), Room 102 (206 NSF), Room 103 (307 NSF)</p> <p>Renovating Building Number - 60, Building Name - TENNIS COURT SUPPORT (0 SS), (430 NSF) Apply Painting, Floor Cover, Electrical, Plumbing, Windows, Lighting, Restrooms, HVAC Systems, Bell/Fire Alarm Systems, Retrofit for Technology, Other to Room 101 (183 NSF), Room 101A (142 NSF), Room 101B (34 NSF), Room 102 (36 NSF), Room 103 (35 NSF) Renovation Description: Renovating Building Number - 60, Building Name - TENNIS COURT SUPPORT (0 SS), (679 NSF) Apply Painting, Floor Cover, Electrical, Plumbing, Windows, Lighting, HVAC Systems, Bell/Fire Alarm Systems, Retrofit for Technology, Other to Room 101 (183 NSF), Room 101A (142 NSF), Room 101B (34 NSF), Room 102 (36 NSF), Room 103 (35 NSF), Room 104 (249 NSF)</p> <p>Renovating Building Number - 60, Building Name - TENNIS COURT SUPPORT (0 SS), (679 NSF) Apply Painting, Floor Cover, Electrical, Plumbing, Windows, Lighting, HVAC Systems, Bell/Fire Alarm Systems, Retrofit for Technology, Other to Room 101 (183 NSF), Room 101A (142 NSF), Room 101B (34 NSF), Room 102 (36 NSF), Room 103 (35 NSF), Room 104 (249 NSF)</p>	63,783
1.071	<p>Renovating Building Number - 62, Building Name - HANDBALL COURTS (0 SS), (357 NSF) Apply Painting, Floor Cover, Electrical, Windows, Lighting, Other to Room 101 (357 NSF) Renovation Description: Renovating Building Number - 62, Building Name - HANDBALL COURTS (0 SS), (357 NSF) Apply Painting, Floor Cover, Electrical, Windows, Lighting, Other to Room 101 (357 NSF)</p> <p>Renovating Building Number - 62, Building Name - HANDBALL COURTS (0 SS), (357 NSF) Apply Painting, Floor Cover, Electrical, Windows, Lighting, Other to Room 101 (357 NSF)</p>	52,954
1.072	<p>Renovating Building Number - 64, Building Name - DUGOUT/PRESSBOX (0 SS), (3707 NSF) Apply Painting, Floor Cover, Electrical, Plumbing, Windows, Lighting, Restrooms, HVAC Systems, Bell/Fire Alarm Systems, Retrofit for Technology, Other to Room 100 (184 NSF), Room 101 (232 NSF), Room 102 (63 NSF), Room 103 (881 NSF), Room 103A (46 NSF), Room 103B (22 NSF), Room 103C (100 NSF), Room 106 (38 NSF), Room 107 (140 NSF), Room 108 (434 NSF), Room 108A (543 NSF), Room 108B (40 NSF), Room 201 (580 NSF), Room 201B (67 NSF), Room 201C (55 NSF), Room 202 (258 NSF), Room 202A (24 NSF) Renovation Description: Renovating Building Number - 64, Building Name - DUGOUT/PRESSBOX (0 SS), (4529 NSF) Apply Painting, Floor Cover, Electrical, Plumbing, Windows, Lighting, HVAC Systems, Bell/Fire Alarm Systems, Retrofit for Technology, Other to Room 100 (184 NSF), Room 101 (232 NSF), Room 102 (63 NSF), Room 103 (881 NSF), Room 103A (46 NSF), Room 103B (22 NSF), Room 103C (100 NSF), Room 104 (104 NSF), Room 105 (38 NSF), Room 106 (38 NSF), Room 107 (140 NSF), Room 108 (434 NSF), Room 108A (543 NSF), Room 108B (40 NSF), Room 109 (358 NSF), Room 110 (217 NSF), Room 150 (52 NSF), Room 201 (580 NSF), Room 201A (53 NSF), Room 201B (67 NSF), Room 201C (55 NSF), Room 202 (258 NSF), Room 202A (24 NSF)</p> <p>Renovating Building Number - 64, Building Name - DUGOUT/PRESSBOX (0 SS), (4529 NSF) Apply Painting, Floor Cover, Electrical, Plumbing, Windows, Lighting, HVAC Systems, Bell/Fire Alarm Systems, Retrofit for Technology, Other to Room 100 (184 NSF), Room 101 (232 NSF), Room 102 (63 NSF), Room 103 (881 NSF), Room 103A (46 NSF), Room 103B (22 NSF), Room 103C (100 NSF), Room 104 (104 NSF), Room 105 (38 NSF), Room 106 (38 NSF), Room 107 (140 NSF), Room 108 (434 NSF), Room 108A (543 NSF), Room 108B (40 NSF), Room 109 (358 NSF), Room 110 (217 NSF), Room 150 (52 NSF), Room 201 (580 NSF), Room 201A (53 NSF), Room 201B (67 NSF), Room 201C (55 NSF), Room 202 (258 NSF), Room 202A (24 NSF)</p>	549,871
1.073	<p>Renovating Building Number - 65, Building Name - SOFTBALL BUILDING (0 SS), (903 NSF) Apply Painting, Floor Cover, Electrical, Plumbing, Windows, Lighting, Restrooms, HVAC Systems, Bell/Fire Alarm Systems, Retrofit for Technology, Other to Room 100 (182 NSF), Room 101 (81 NSF), Room 104 (320 NSF), Room 105 (320 NSF) Renovation Description: Renovating Building Number - 65, Building Name - SOFTBALL BUILDING (0 SS), (974 NSF) Apply Painting, Floor Cover, Electrical, Plumbing, Windows, Lighting, HVAC Systems, Bell/Fire Alarm Systems, Retrofit for Technology, Other to Room 100 (182 NSF), Room 101 (81 NSF), Room 102 (35 NSF), Room 103 (36 NSF), Room 104 (320 NSF), Room 105 (320 NSF)</p> <p>Renovating Building Number - 65, Building Name - SOFTBALL BUILDING (0 SS), (974 NSF) Apply Painting, Floor Cover, Electrical, Plumbing, Windows, Lighting, HVAC Systems, Bell/Fire Alarm Systems, Retrofit for Technology, Other to Room 100 (182 NSF), Room 101 (81 NSF), Room 102 (35 NSF), Room 103 (36 NSF), Room 104 (320 NSF), Room 105 (320 NSF)</p>	133,945
1.074	<p>Renovating Building Number - 66, Building Name - WOMEN'S SOFTBALL LCK (0 SS), (1128 NSF) Apply Painting, Floor Cover, Electrical, Plumbing, Windows, Lighting, Restrooms, HVAC Systems, Bell/Fire Alarm Systems, Retrofit for Technology, Other to Room 100 (445 NSF), Room 101 (235 NSF), Room 102 (78 NSF), Room 103 (59 NSF), Room 104 (205 NSF), Room 105 (46 NSF), Room 106 (27 NSF), Room 107 (33 NSF) Renovation Description: Renovating Building Number - 66, Building Name - WOMEN'S SOFTBALL LCK (0 SS), (1128 NSF) Apply Painting, Floor Cover, Electrical, Plumbing, Windows, Lighting, HVAC Systems, Bell/Fire Alarm Systems, Retrofit for Technology, Other to Room 100 (445 NSF), Room 101 (235 NSF), Room 102 (78 NSF), Room 103 (59 NSF), Room 104 (205 NSF), Room 105 (46 NSF), Room 106 (27 NSF), Room 107 (33 NSF)</p>	167,320

EDUCATIONAL PLANT FIVE YEAR SURVEY REPORT

College:

Survey:

Status:

3-COLLEGE OF CENTRAL FLORIDA

Survey : 3 Version : 2

Active Pending

1.075	<p>Renovating Building Number - 66, Building Name - WOMEN'S SOFTBALL LCK (0 SS), (1128 NSF) Apply Painting, Floor Cover, Electrical, Plumbing, Windows, Lighting, HVAC Systems, Bell/Fire Alarm Systems, Retrofit for Technology, Other to Room 100 (445 NSF), Room 101 (235 NSF), Room 102 (78 NSF), Room 103 (59 NSF), Room 104 (205 NSF), Room 105 (46 NSF), Room 106 (27 NSF), Room 107 (33 NSF)</p> <p>Renovating Building Number - 67, Building Name - BASEBALL BATTING CAG (0 SS), (3103 NSF) Apply Painting, Floor Cover, Electrical, Plumbing, Windows, Lighting, Restrooms, HVAC Systems, Bell/Fire Alarm Systems, Retrofit for Technology, Other to Room 101 (3103 NSF) Renovation Description: Renovating Building Number - 67, Building Name - BASEBALL BATTING CAG (0 SS), (3103 NSF) Apply Painting, Floor Cover, Electrical, Plumbing, Lighting, Retrofit for Technology, Other to Room 101 (3103 NSF)</p> <p>Renovating Building Number - 67, Building Name - BASEBALL BATTING CAG (0 SS), (3103 NSF) Apply Painting, Floor Cover, Electrical, Plumbing, Lighting, Retrofit for Technology, Other to Room 101 (3103 NSF)</p>	460,278
1.076	<p>Renovating Building Number - 68, Building Name - SOFTBALL BATTING CAG (0 SS), (3058 NSF) Apply Painting, Floor Cover, Electrical, Plumbing, Windows, Lighting, Restrooms, HVAC Systems, Bell/Fire Alarm Systems, Retrofit for Technology, Other to Room 101 (2932 NSF), Room 102 (126 NSF) Renovation Description: Renovating Building Number - 68, Building Name - SOFTBALL BATTING CAG (0 SS), (3058 NSF) Apply Painting, Floor Cover, Electrical, Lighting, Retrofit for Technology, Other to Room 101 (2932 NSF), Room 102 (126 NSF)</p> <p>Renovating Building Number - 68, Building Name - SOFTBALL BATTING CAG (0 SS), (3058 NSF) Apply Painting, Floor Cover, Electrical, Lighting, Retrofit for Technology, Other to Room 101 (2932 NSF), Room 102 (126 NSF)</p>	453,603
1.077	<p>Renovating Building Number - 5, Building Name - STUDENT UNION/PAT. C (0 SS), (35803 NSF) Apply Painting, Floor Cover, Electrical, Plumbing, Windows, Lighting, Restrooms, HVAC Systems, Bell/Fire Alarm Systems, Retrofit for Technology to Room 100 (1426 NSF), Room 100C (48 NSF), Room 100G (240 NSF), Room 100H (1450 NSF), Room 101 (979 NSF), Room 101A (176 NSF), Room 101B (165 NSF), Room 101C (164 NSF), Room 101D (74 NSF), Room 101E (73 NSF), Room 101F (70 NSF), Room 101G (296 NSF), Room 102 (2054 NSF), Room 102A (198 NSF), Room 102B (232 NSF), Room 102C (97 NSF), Room 102D (95 NSF), Room 102E (95 NSF), Room 102F (95 NSF), Room 102G (98 NSF), Room 102H (98 NSF), Room 102J (82 NSF), Room 102K (82 NSF), Room 102L (82 NSF), Room 102M (127 NSF), Room 102N (82 NSF), Room 102P (96 NSF), Room 102Q (128 NSF), Room 102R (96 NSF), Room 102S (48 NSF), Room 102T (147 NSF), Room 103 (4190 NSF), Room 103A (486 NSF), Room 103B (1071 NSF), Room 103C (580 NSF), Room 103D (122 NSF), Room 103E (103 NSF), Room 103F (85 NSF), Room 103G (47 NSF), Room 103H (207 NSF), Room 103I (537 NSF), Room 103J (80 NSF), Room 104 (1294 NSF), Room 105 (786 NSF), Room 106 (2744 NSF), Room 106B (139 NSF), Room 106C (185 NSF), Room 106H (208 NSF), Room 107 (35 NSF), Room 200 (1450 NSF), Room 200C (31 NSF), Room 200D (84 NSF), Room 200F (93 NSF), Room 200G (240 NSF), Room 200H (75 NSF), Room 201 (1536 NSF), Room 201A (108 NSF), Room 201B (158 NSF), Room 201C (94 NSF), Room 201D (94 NSF), Room 201G (93 NSF), Room 201H (93 NSF), Room 201K (93 NSF), Room 201L (142 NSF), Room 201M (96 NSF), Room 201P (96 NSF), Room 201Q (96 NSF), Room 201R (96 NSF), Room 201S (142 NSF), Room 201T (157 NSF), Room 202 (632 NSF), Room 202A (187 NSF), Room 202B (455 NSF), Room 202C (51 NSF), Room 203 (717 NSF), Room 204 (1662 NSF), Room 204A (85 NSF), Room 204B (128 NSF), Room 204C (150 NSF), Room 204D (120 NSF), Room 204E (55 NSF), Room 204F (243 NSF), Room 204G (102 NSF), Room 204H (100 NSF), Room 204J (100 NSF), Room 204K (103 NSF), Room 205 (427 NSF), Room 205A (250 NSF), Room 205B (176 NSF), Room 205C (112 NSF), Room 205E (113 NSF), Room 205F (110 NSF), Room 205G (112 NSF), Room 205H (164 NSF), Room 205J (142 NSF), Room 205K (151 NSF), Room 205L (507 NSF), Room 205M (512 NSF), Room 205N (476 NSF), Room 205P (385 NSF), Room 205Q (82 NSF), Room 207 (35 NSF) Renovation Description: Renovating Building Number - 5, Building Name - STUDENT UNION/PAT. C (0 SS), (9588 NSF) Apply Painting, Floor Cover, Electrical, Plumbing, Windows, Lighting, HVAC Systems, Bell/Fire Alarm Systems, Retrofit for Technology, Other to Room 103 (4190 NSF), Room 103A (486 NSF), Room 103B (1071 NSF), Room 103C (580 NSF), Room 103D (122 NSF), Room 103E (103 NSF), Room 103F (85 NSF), Room 103G (47 NSF), Room 103H (207 NSF), Room 103I (537 NSF), Room 103J (80 NSF), Room 104 (1294 NSF), Room 105 (786 NSF)</p> <p>Renovating Building Number - 5, Building Name - STUDENT UNION/PAT. C (0 SS), (9588 NSF) Apply Painting, Floor Cover, Electrical, Plumbing, Windows, Lighting, HVAC Systems, Bell/Fire Alarm Systems, Retrofit for Technology, Other to Room 103 (4190 NSF), Room 103A (486 NSF), Room 103B (1071 NSF), Room 103C (580 NSF), Room 103D (122 NSF), Room 103E (103 NSF), Room 103F (85 NSF), Room 103G (47 NSF), Room 103H (207 NSF), Room 103I (537 NSF), Room 103J (80 NSF), Room 104 (1294 NSF), Room 105 (786 NSF)</p>	5,310,778
1.078	<p>Renovating Building Number - 71, Building Name - THE WEBBER CENTER (0 SS), (7069 NSF) Apply Painting, Floor Cover, Electrical, Plumbing, Windows, Lighting, Restrooms, HVAC Systems, Bell/Fire Alarm Systems, Retrofit for Technology to Room 100 (333 NSF), Room 100B (182 NSF), Room 100C (170 NSF), Room 101 (1944 NSF), Room 102 (416 NSF), Room 103A</p>	1,048,568

EDUCATIONAL PLANT FIVE YEAR SURVEY REPORT

College:

3-COLLEGE OF CENTRAL FLORIDA

Survey:

Survey : 3 Version : 2

Status:

Active Pending

(110 NSF), Room 103B (194 NSF), Room 103C (30 NSF), Room 104 (254 NSF), Room 104D (525 NSF), Room 104E (20 NSF), Room 105 (2555 NSF), Room 105A (336 NSF)
Renovation Description: Renovating Building Number - 71, Building Name - THE WEBBER CENTER (0 SS), (8548 NSF) Apply Painting, Floor Cover, Electrical, Plumbing, Windows, Lighting, HVAC Systems, Bell/Fire Alarm Systems, Retrofit for Technology, Other to Room 100 (333 NSF), Room 100A (81 NSF), Room 100B (182 NSF), Room 100C (170 NSF), Room 100D (82 NSF), Room 101 (1944 NSF), Room 102 (416 NSF), Room 103 (434 NSF), Room 103A (110 NSF), Room 103B (194 NSF), Room 103C (30 NSF), Room 104 (254 NSF), Room 104A (141 NSF), Room 104B (91 NSF), Room 104C (21 NSF), Room 104D (525 NSF), Room 104E (20 NSF), Room 105 (2555 NSF), Room 105A (336 NSF), Room 106 (269 NSF), Room 107 (139 NSF), Room 108 (221 NSF)

Renovating Building Number - 71, Building Name - THE WEBBER CENTER (0 SS), (8548 NSF) Apply Painting, Floor Cover, Electrical, Plumbing, Windows, Lighting, HVAC Systems, Bell/Fire Alarm Systems, Retrofit for Technology, Other to Room 100 (333 NSF), Room 100A (81 NSF), Room 100B (182 NSF), Room 100C (170 NSF), Room 100D (82 NSF), Room 101 (1944 NSF), Room 102 (416 NSF), Room 103 (434 NSF), Room 103A (110 NSF), Room 103B (194 NSF), Room 103C (30 NSF), Room 104 (254 NSF), Room 104A (141 NSF), Room 104B (91 NSF), Room 104C (21 NSF), Room 104D (525 NSF), Room 104E (20 NSF), Room 105 (2555 NSF), Room 105A (336 NSF), Room 106 (269 NSF), Room 107 (139 NSF), Room 108 (221 NSF)

OCALA CAMPUS **Total :** 100,602,768

EDUCATIONAL PLANT FIVE YEAR SURVEY REPORT

College:

3-COLLEGE OF CENTRAL FLORIDA

Survey:

Survey : 3 Version : 2

Status:

Active Pending
